

Iron 8933
ANNUAL SURVEYS.

3522

No. Survey held at London Date 8th 10th March 18 71
on the Sewer "Spartan" Master C. Redhead
Tonnage 1200 Built at Glasgow When built 1868
By whom built Laurie Owners M. Spartali
Port belonging to London Destined Voyage Odessa
If Surveyed Afloat or in Dry Dock Reed's Dry Dock.

Recd 12.4.71

Last Survey, No. 7705 Port of Iron. Classed B1 Iron Deck
1, 70.

The present Condition of the

Decks	} <u>Good</u>	Treenails <u>Rivets</u>	} <u>Good</u>	Windlass and Capstan	} <u>Good and</u>
Waterways		Breasthooks and Stems		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the Openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Ditto ditto at other places		Sails	
Planksheers	} <u>where</u>	Keelsons	} <u>where</u>	Anchors No. of	} <u>complete</u>
Sheerstrakes		Clamps and Shelves		Cables	
Topsides		Ceiling		Hawsers and Warps	
Wales	} <u>seen.</u>	Rudder	} <u>where seen.</u>	Standing & Running Rigging	} <u> </u>
Plank (Bottom) and Counter		Copper <u>Cemented</u> When put on <u>1/68.</u>			

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good where examined.

Outside cleaned and painted - bottom coated with the same
Composition. Defective rivets in rudder renewed.
Is now in good and efficient condition, and fit in my opinion
to remain classed B1.

Committee's Minute 14th April 18 71

J. H. Eastlake,

Character assigned B1

Certificate (if required)

No. 149 Survey held at London Date 6th April 18 71
on the Iron Steamer "St. Carolina" Master Shaw
Tonnage 1173 Built at Blackburn When built 1860-12 mo.
By whom built Richardson Owners J. Galbraith & Co
Port belonging to London Destined Voyage Mediterranean
If Surveyed Afloat or in Dry Dock Wigram's Dry Dock

Last Survey, No. 8410 Port of Iron. Classed B1
"SS 1870" 10-70

The present Condition of the

Decks	} <u>Good where seen</u>	Treenails <u>Rivets</u>	} <u>Good where seen</u>	Windlass and Capstan	} <u>Good and</u>
Waterways		Breasthooks and Stems		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the Openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Ditto ditto at other places		Sails	
Planksheers	} <u>where seen</u>	Keelsons	} <u>where seen</u>	Anchors No. of	} <u> </u>
Sheerstrakes		Clamps and Shelves		Cables	
Topsides		Ceiling		Hawsers and Warps	
Wales	} <u> </u>	Rudder	} <u> </u>	Standing & Running Rigging	} <u> </u>
Plank (Bottom) and Counter		Copper <u> </u> When put on <u> </u>			

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good where examined

Bottom cleaned and coated with Paint and Gallon.
Is now in good and efficient condition and in my opinion
deserve to remain classed B1.

Committee's Minute 14th April 18 71

Character assigned B1

Certificate (if required)

© 2019 Lloyd's Register Foundation

IRON448-0284