

ANNUAL SURVEYS.

No. 363 Survey held at London Date April 10th to 13th 1871
 on the Ship "Horsa" Master W. Kinlay
 Tonnage 1094 Built at Greenock When built 1860 - 7 mcs
 By whom built Scott & Owners Rathbone B^{rs}
 Port belonging to Liverpool Destined Voyage Cardiff
 If Surveyed Afloat or in Dry Dock Bigrand Dry Dock

Last Survey, No. 6203 Port of Iron. Classified * A. 1 SS 202 568

The present Condition of the

| | | | | | |
|-----------------------------------|--|--------------------------------------|----------------|-------------------------------|------------|
| Decks | Good | Rivets | When seen good | Windlass and Capstan | Good |
| Waterways | " | Tree-nails | " | Pumps | " |
| Comings | " | Breasthooks and Stemson | " | Boats | Four |
| Upper Deck Beams & Fastenings | " | Transoms, Pointers, and Crutches | " | Masts, Yards, &c. | " |
| Lower Deck Beams & Fastenings | " | Timbers of the Frame at the Openings | " | Sails | " |
| Planksheers | " | Ditto ditto at other places | " | Anchors No. of 3 B. 1 L. 2 H. | " |
| Sheerstrakes | " | Keelsons | " | Cables | Good |
| Topsides | " | Clamps and Shelves | " | Hawsers and Warps | And |
| Wales | " | Ceiling | " | Standing & Running Rigging | Sufficient |
| Plate | " | Rudder | " | | |
| Plank (Bottom) and Counter | " | Copper Cement When put on 1868 | " | | |
| General Observations and Opinion, | Caulking of Bottom, Deck, and Waterways Good | | | | |

The Bottom, cleaned and painted. Rudder
 braces refitted. She is now in good condition and in
 my opinion eligible to remain as classed.

Committee's Minute 25th April 1871

Character assigned

* A. 1

J. Lawrence

Certificate (if required)

No. 139 Survey held at London Date April 14th to 20th 1871
 on the Ship "Ben Nevis" Master A. W. Petrie
 Tonnage 1055 Built at Glasgow When built 1868 - 6 mcs
 By whom built Barclay & Owners Watson B^{rs}
 Port belonging to Glasgow Destined Voyage Glasgow
 If Surveyed Afloat or in Dry Dock Pontons Victoria Dock

Last Survey, No. 8010 Port of Iron. Classified * A. 1 670

The present Condition of the

| | | | | | |
|-----------------------------------|--|--------------------------------------|----------------|-------------------------------|------------|
| Decks | Good | Rivets | When seen good | Windlass and Capstan | Good |
| Waterways | " | Tree-nails | " | Pumps | " |
| Comings | " | Breasthooks and Stemson | " | Boats | Four |
| Upper Deck Beams & Fastenings | " | Transoms, Pointers, and Crutches | " | Masts, Yards, &c. | " |
| Lower Deck Beams & Fastenings | " | Timbers of the Frame at the Openings | " | Sails | " |
| Planksheers | " | Ditto ditto at other places | " | Anchors No. of 3 B. 1 L. 2 H. | " |
| Sheerstrakes | " | Keelsons | " | Cables | Good |
| Topsides | " | Clamps and Shelves | " | Hawsers and Warps | And |
| Wales | " | Ceiling | " | Standing & Running Rigging | Sufficient |
| Plate | " | Rudder | " | | |
| Plank (Bottom) and Counter | " | Copper Cement When put on 1868 | " | | |
| General Observations and Opinion, | Caulking of Bottom, Deck, and Waterways Good | | | | |

The Bottom, cleaned and coated with a
 composition. She is now, when seen in good condition
 and in my opinion eligible to remain as classed.

Committee's Minute 25th April 1871

Character assigned

* A. 1

J. Lawrence

Certificate (if required).

IRON 448-0294