

# ANNUAL SURVEYS.

8990  
33584

No. 659 Survey held at London Date 27<sup>th</sup> Apr. & May 1871-  
on the *Hon. Park "Merle"* Master *S. Sim*  
Tonnage 287 Built at London When built 1863-11 mo  
By whom built *Westwood &* Owners *Serattou Sons & Co*  
Port belonging to London Destined Voyage *West Indies*  
If Surveyed Afloat or in Dry Dock *Union dry dock.*

Last Survey, No. 8380 Port of *Iron.* Classed *\*FAI*  
(S.S.M-67) 10.70

The present Condition of the

Decks	Tree-nails <i>Rivets</i>	Windlass and Capstan
Waterways	Breasthooks and Stems	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper <i>Lead</i> When put on 1863	

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways *Good where examined*  
*Bottom cleaned and coated with Black Varnish.*  
*Is now in good and efficient condition and in my opinion eligible to remain as classed.*  
Committee's Minute 9<sup>th</sup> May 1871  
Character assigned *A 1*  
Certificate (if required)

No. 838 Survey held at London Date 29 Apr. 1871-  
on the *Hon. Park "Mountain Laurel"* Master *Dickson*  
Tonnage 690 Built at *Harrington* When built 1865-2 mo  
By whom built *Williamson* Owners *Sprott & Co*  
Port belonging to *Liverpool* Destined Voyage *India*  
If Surveyed Afloat or in Dry Dock *Lincoln dry dock.*

Last Survey, No. 7132 Port of *Iron.* Classed *\*FAI*  
(S.S.M-69) 6.69

The present Condition of the

Decks	Tree-nails <i>Rivets</i>	Windlass and Capstan
Waterways	Breasthooks and Stems	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper <i>Lead</i> When put on 1869	

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways *Good where examined*  
*Bottom cleaned and coated with patent composition*  
*Steering gear repaired. Is now in good and efficient condition*  
*and in my opinion eligible to remain as classed.*  
Committee's Minute 9<sup>th</sup> May 1871  
Character assigned *A 1*  
Certificate (if required)