

ANNUAL SURVEYS.

No. 1145 Survey held at Newcastle Date April 6th 18 71
 on the S.S. "Hilda" Master J. Mottou
 Tonnage 650 Built at Glasgow When built 1865-5-10
 By whom built Reid Owners Hetherington Mining Co. (Ld.)
 Port belonging to London Destined Voyage Norway
 If Surveyed Afloat or in Dry Dock Palmer's dock

Last Survey, No. 8679 Port of Tromsø (S.S. No. 2-69) Classed B.T. 11-70

The present Condition of the

Decks <u>good where seen</u>	Rivets <u>good where seen</u>	Windlass and Capstan <u>good</u>
Waterways <u>do</u>	Treenails <u>good where seen</u>	Pumps <u>do</u>
Comings <u>do</u>	Breasthooks and Stemson <u>do</u>	Boats <u>do</u>
Upper Deck Beams & Fastenings <u>do</u>	Transoms, Pointers, and Crutches <u>do</u>	Masts, Yards, &c. <u>do</u>
Lower Deck Beams & Fastenings <u>do</u>	Timbers of the Frame at the Openings <u>do</u>	Sails <u>Sufficient</u>
Planksheers <u>do</u>	Ditto ditto at other places <u>do</u>	Anchors No. of <u>do</u>
Sheerstrakes <u>do</u>	Keelsons <u>do</u>	Cables <u>do</u>
Topsides <u>do</u>	Clamps and Shelves <u>do</u>	Hawsers and Warps <u>do</u>
Wales <u>do</u>	Ceiling <u>do</u>	Standing & Running Rigging <u>do</u>
Plank (Bottom) and Counter <u>do</u>	Rudder <u>do</u>	
	Copper <u>When put on</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good where seen

The bottom has now been scraped and painted, and a new propeller supplied. She appears to be in good and efficient condition, and eligible, in my opinion, to remain as classed.

Committee's Minute 2nd June 18 71Character assigned B

J.P. Reid.
Special (Damage Survey)
2.2.0 Certificate (if required).

No. _____ Survey held at _____ Date _____ 18 ____
 on the _____ Master _____
 Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____

The present Condition of the

Decks _____	Treenails _____	Windlass and Capstan _____
Waterways _____	Breasthooks and Stemson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame at the Openings _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings _____	Ditto ditto at other places _____	Sails _____
Planksheers _____	Keelsons _____	Anchors No. of _____
Sheerstrakes _____	Clamps and Shelves _____	Cables _____
Topsides _____	Ceiling _____	Hawsers and Warps _____
Wales _____	Rudder _____	Standing & Running Rigging _____
Plank (Bottom) and Counter _____	Copper _____ When put on _____	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways _____

Committee's Minute _____ 18 ____

Character assigned _____



© 2019

Lloyd's Register

Certificate (if required).