

ANNUAL SURVEYS.

Rec 14/6/71

No. 22842 Survey held at Liverpool. Date 10 May to 2 June 1871
 on the BARQUE POLESTAR Master Brown
 Tonnage 647 Built at Hull. When built 1858
 By whom built _____ Owners Colesworth
 Port belonging to Liverpool. Destined Voyage Valparaiso
 If Surveyed Afloat or in Dry Dock Canning Dry Dock.

Last Survey, No. 7330 Port of Iron. Classified * A. S.
S. S. 1293. 69. P. 69.

The present Condition of the

Decks	Trunnels <u>Rivets</u>	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper <u>Cement</u> When put on <u>1860.</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good what seen

Bottom scraped and painted. She is now in good condition and eligible - in my opinion to remain as classed.

Committee's Minute Liverpool 13th June 1871 James Purdie

Character assigned * A / M

Certificate (if required)

No. _____ Survey held at Liverpool. Date 18 May to 3 June 1871
 on the BARQUE "OLANO" Master Sarricaga
 Tonnage 445 Built at Belfast. When built 1863. 9. mo
 By whom built Harland. Owners Clau & Co.
 Port belonging to Bilbao Destined Voyage Havana
 If Surveyed Afloat or in Dry Dock Canning Dry Dock.

Last Survey, No. 6974 Port of Iron. Classified * A. S.
S. S. 1201. 68. 9. 68.

The present Condition of the

Decks	Trunnels <u>Rivets</u>	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper <u>Cement</u> When put on <u>1863.</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good what seen

Bottom scraped and painted. She is now in good condition and eligible - in my opinion to remain as classed.

Committee's Minute Liverpool 13th June 1871 James Purdie

Character assigned * A / M

Certificate (if required)

IRON448-0429

"Palestani"
22.842
"Claro"



© 2019

Lloyd's Register
Foundation