

ANNUAL SURVEYS.

No. 2287 Survey held at Liverpool. Date 22 May to 20 June 18 71
 on the SHIP "AMINTA" Master W. Maylor
 Tonnage 1132 Built at Liverpool. When built 1862. 2. mo
 By whom built Lones. Owners J. Sonany & Co
 Port belonging to Liverpool. Destined Voyage Calcutta.
 If Surveyed Afloat or in Dry Dock Clearance Dry Dock.

Last Survey, No. 6580 Port of Liverpool. Classed * A. S.
 5.5.1862. 68. 10.68.

The present Condition of the

Decks	Tree-nails <u>Reels</u> .	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper <u>Cement</u> When put on <u>1864</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good where seen.

Bottom scraped and painted. She is now in good condition. Eligible in my opinion to remain as classed.

Committee's Minute Liverpool 11. July 1871

Character assigned * A

Certificate (if required)

No. 250 Survey held at Liverpool. Date 22 June to 10 July 18 71
 on the SHIP GLENHUNTLY Master J. W. Large
 Tonnage 547 Built at P. Glasgow. When built 1862. 4. mo.
 By whom built Raid Owners Johnston & Co.
 Port belonging to Liverpool. Destined Voyage Otago.
 If Surveyed Afloat or in Dry Dock Caulking Dry Dock.

Last Survey, No. 8057 Port of Liverpool. Classed * A. S.
 5.5.1862. 70. 6.70.

The present Condition of the

Decks	Tree-nails <u>Reels</u> .	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper <u>Cement</u> When put on <u>1862</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good where seen.

Bottom scraped and painted. She is now in good condition. Eligible in my opinion to remain as classed.

Committee's Minute Liverpool 11. July 1871

Character assigned * A

Certificate (if required)

Aminta

Glenhumbly 22841



© 2019

Lloyd's Register
Foundation