

# ANNUAL SURVEYS.

387 No. 1079 Survey held at London Date 10<sup>th</sup> 19<sup>th</sup> July 1871  
 on the iron ship "Korrah" Master Wm Greaves  
 Tonnage 1098 Built at Switzerland When built 1864 - 6 mo.  
 By whom built Pile Owners G. D. Lyser  
 Port belonging to London Destined Voyage Calcutta, via Liverpool,  
 If Surveyed Afloat or in Dry Dock Midrams' Dry Dock and Afloat.

Last Survey, No. 8124 Port of Trow. Classified SAI

The present Condition of the

Decks  
 Waterways  
 Comings  
 Upper Deck Beams & Fastenings  
 Lower Deck Beams & Fastenings  
 Planksheers  
 Sheerstrakes  
 Topsides  
 Wales  
 Plank (Bottom) and Counter

Treeails Rivets  
 Breasthooks and Stemson  
 Transoms, Pointers, and Crutches  
 Timbers of the Frame at the Openings  
 Ditto ditto at other places  
 Keelsons  
 Clamps and Shelves  
 Ceiling  
 Rudder  
 Copper 10m<sup>t</sup> When put on 1864

Windlass and Capstan  
 Pumps  
 Boats  
 Masts, Yards, &c.  
 Sails  
 Anchors No. of  
 Cables  
 Hawser and Warps  
 Standing & Running Rigging

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good where Examined

Bottom cleaned and coated with Paint and Gallon.  
Mizen Mast, Mizen topsail yard, fore and main topmasts, and  
the fore and main yards, new of Pine. Is now in good and  
efficient condition, and in my opinion eligible to remain  
 Committee's Minute 21<sup>st</sup> July 1871

Character assigned

Certificate (if required)

120447-0080