

ANNUAL SURVEYS.

No. 47 Survey held at London Date 14th June 19th 18 71
 on the Iron Ship Indian Empire Master J. H. Blackmore
 Tonnage 1515 Built at West Hartlepool When built 1865 ^{1st msk}
 By whom built Pile Owners Duncan & Co.
 Port belonging to London Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock Thames dry dock

Last Survey, No. 8170 Port of Iron Classed A. 1. S. S. No 1 / 69
8170

The present Condition of the

	<u>good</u>	<u>Greenails</u> Rivets where seen <u>good</u>	Windlass and Capstan <u>in good order</u>
Decks	//	Breasthooks and Stemson	//
Waterways	//	Transoms, Pointers, and Crutches	//
Comings	//	Timbers of the Frame at the Openings	//
Upper Deck Beams & Fastenings	//	Ditto ditto at other places	//
Lower Deck Beams & Fastenings	//	Keelsons	//
Planksheers	//	Clamps and Shelves	//
Sheerstrakes	//	Ceiling	//
Topsides	//	Rudder <u>efficient</u>	//
Wales	//	Copper <u>When put on</u>	//
Plank (Bottom) and Counter	//		//

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good

Cleaned the bottom, and payd it with Linx and tallow.

Is now in good condition and entitled to remain

as Class'd A. 1.

Samuel Prentiss

Committee's Minute 4th July 18 71

Character assigned A 1

Certificate (if required)

No. 298 Survey held at London Date 16th June 19th 18 71
 on the Iron Ship Portland Master Charles Cooke
 Tonnage 872 Built at Port Glasgow When built 1862 ^{6th msk}
 By whom built Reed Owners Temperley &
 Port belonging to London Destined Voyage Shanghai
 If Surveyed Afloat or in Dry Dock Greens lower Dock & East India docks

Last Survey, No. 8103 Port of Iron Classed A. 1. S. S. No 2 / 68
710

The present Condition of the

	<u>good</u>	<u>Greenails</u> Rivets where seen <u>good</u>	Windlass and Capstan <u>in good order</u>
Decks	//	Breasthooks and Stemson	//
Waterways	//	Transoms, Pointers, and Crutches	//
Comings	//	Timbers of the Frame at the Openings	//
Upper Deck Beams & Fastenings	//	Ditto ditto at other places	//
Lower Deck Beams & Fastenings	//	Keelsons	//
Planksheers	//	Clamps and Shelves	//
Sheerstrakes	//	Ceiling	//
Topsides	//	Rudder <u>efficient</u>	//
Wales	//	Copper <u>When put on</u>	//
Plank (Bottom) and Counter	//		//

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good

Cleaned and recoated the bottom.

She is, as far as seen, in good condition and entitled in my opinion to remain as class'd

A. 1.

Samuel Prentiss

Committee's Minute 4th July 18 71

Character assigned A 1

Certificate (if required)

1862/449-0081

Portland
Indian Empire



© 2019

Lloyd's Register
Foundation