

48 No. 9256 Survey held at London Date 14<sup>th</sup> Aug<sup>r</sup> 1871 31803  
on the iron ship "Zealandia" Master J. White  
Tonnage 1116 Built at Glasgow When built 1869-6 mo  
By whom built Connell Owners Sharr. Savill & Co.  
Port belonging to London Destined Voyage New Zealand  
If Surveyed Afloat or in Dry Dock Blackwall Point Dry Dock.

Last Survey, No. 8197

Port of Iron

Classed

\*  
SAI  
8.70

The present Condition of the

Decks

Waterways

ings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

strakes

Wales

Plank (Bottom) and Counter

General Observations and Opinion,

Remains

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the Openings

Ditto ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper

When put on 1869

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Sails

Anchors, No. of

Cables

Hawsers and Warps

Standing and Running Rigging

Caulking of Bottom, Deck, and Waterways

Bottom cleaned and coated with patent composition  
Is now in good, and efficient condition, and in  
my opinion eligible to remain as  
Classed.

Committee's Minute

15<sup>th</sup> August 1871

Character assigned

\*  
A

ITW J. A. Turner

Certificate (if required).