

# ANNUAL SURVEYS.

No. 575 Survey held at London Date 14<sup>th</sup> August 1871  
 on the iron ship City of Madras Master C. Graham  
 Tonnage 999 Built at Glasgow When built 1859-9 mo  
 By whom built Stephen Owners Smith & Sons  
 Port belonging to Glasgow Destined Voyage Sydney  
 If Surveyed Afloat or in Dry Dock in the Port of Victoria Dock

Last Survey, No. 8476 Port of Iron Classed \*A/1  
 The present Condition of the 5.5.1871 11.70

Decks	Freemasts <u>Pure</u>	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors, No. of
Sheerstrakes	Clamps and Shells	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing and Running Rigging
Plank (Bottom) and Counter	Copper <u>Asph.</u> When put on <u>1859</u>	

General Observations and Opinion, Good where examined  
Riggers pintles repaired. Bottom cleaned and coated with  
Mc. Smith's composition. Is now in good and efficient  
condition, and in my opinion eligible to remain as classed.  
 Committee's Minute 18<sup>th</sup> August 1871  
 Character assigned \*A/1 ITW W. H. Turner  
 Certificate (if required).

No. 160 Survey held at London Date 10<sup>th</sup> August 1871  
 on the iron ship "Perar" Master Dix  
 Tonnage 902 Built at Sunderland When built 1863-9 mo  
 By whom built Pile Owners G. D. Syser  
 Port belonging to London Destined Voyage Madras  
 If Surveyed Afloat or in Dry Dock in a dry dock and afloat

Last Survey, No. 8117 Port of Iron Classed \*A/1 SS 17/1 68  
 The present Condition of the 7.70

Decks	Freemasts <u>Pure</u>	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors, No. of
Sheerstrakes	Clamps and Shells	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing and Running Rigging
Plank (Bottom) and Counter	Copper <u>sem.</u> When put on <u>1863</u>	

General Observations and Opinion, Good where examined  
Pop covering board extending around Stern and Quarters  
renewed of Leaky. Bottom cleaned and coated with Dammato  
Enamel. Is now in good and efficient condition and  
in my opinion eligible to remain  
 Committee's Minute 18<sup>th</sup> August 1871  
 Character assigned \*A/1 ITW W. H. Turner  
 Certificate (if required).