

# ANNUAL SURVEYS.

9304

~~57826~~

No. 404 Survey held at London Date 17<sup>th</sup> Aug<sup>r</sup> 71  
 on the iron hull of the ship Master Robinson  
 Tonnage 2481 Built at Glasgow When built 1870 - 6 mo  
 By whom built Napier Owners Sham Mayton & Co  
 Port belonging to London Destined Voyage China  
 If Surveyed Afloat or in Dry Dock Shames Lim<sup>d</sup> Docks

Last Survey, No. 8796 Port of Iron Classed 100 A1

The present Condition of the

Decks	Tree-nails <u>None</u>	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shells	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper <u>None</u> When put on <u>1870</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good where examined  
Inside clean and painted, bottom scraped and coated with  
paint and Peacock's St. Hippo position.  
Shown in good and efficient condition, and in my  
opinion eligible to remain as classed.

Committee's Minute 25<sup>th</sup> August 1871

Character assigned 100 A1

Certificate (if required).

1200449-0208