

9332
ANNUAL SURVEYS.

No. 534 **No. 2908** Survey held at West Hartlepool Date 1st September 1871
 in Register on the S.S. "Ann Webster" Master Blackburn
Wharfedale Tonnage 746 Built at Hartlepool When built 1870
 By whom built W. H. H. & Co. Owners Hill & Co.
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock In Dry Dock

Last Survey, No. 2769 Port of Iron. Classed 90 A1
2.71

The present Condition of the

Decks Good, now painted
 Waterways _____
 Comings _____
 Upper Deck Beams & Fastenings _____
 Lower Deck Beams & Fastenings _____
 Planksheers _____
 Sheerstrakes _____
 Topsides _____
 Wales _____
 Plank (Bottom) and Counter _____

Treenails Pluto
 Breasthooks and Stemson _____
 Transoms, Pointers, and Crutches _____
 Timbers of the Frame _____ at the Openings
 Do Do at other places _____
 Keelsons _____
 Clamps and Shelves _____
 Ceiling _____
 Rudder _____
 Copper _____ When put on _____

Windlass and Capstan _____
 Pumps _____
 Boats _____
 Masts, Yards, &c. _____
 Sails _____
 Anchors No. of _____
 Cables _____
 Hawser and Warps _____
 Standing & Running Rigging _____

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good

*Is now in a good & efficient state fit for the safe conveyance of
 dry & perishable goods, & from all parts of the World, & may in my
 opinion remain as now classed 90 A1.*

Committee's Minute 8th September 1871

Character assigned 90 A1

J. P. Gladstone
J. B. M.

Certificate (if required)

No. _____ Survey held at _____ Date _____ 18____
 on the _____ Master _____
 Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____

The present Condition of the

Decks _____
 Waterways _____
 Comings _____
 Upper Deck Beams & Fastenings _____
 Lower Deck Beams & Fastenings _____
 Planksheers _____
 Sheerstrakes _____
 Topsides _____
 Wales _____
 Plank (Bottom) and Counter _____

Treenails _____
 Breasthooks and Stemson _____
 Transoms, Pointers, and Crutches _____
 Timbers of the Frame _____ at the Openings
 Do Do at other places _____
 Keelsons _____
 Clamps and Shelves _____
 Ceiling _____
 Rudder _____
 Copper _____ When put on _____

Windlass and Capstan _____
 Pumps _____
 Boats _____
 Masts, Yards, &c. _____
 Sails _____
 Anchors No. of _____
 Cables _____
 Hawser and Warps _____
 Standing & Running Rigging _____

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways _____

Committee's Minute _____ 18____

Character assigned _____



© 2019

Lloyd's Register
 Foundation

Certificate (if required).