

9352
ANNUAL SURVEYS.

~~37866~~

No. _____ Survey held at Lond Date 20th August 1871
 on the iron ship Vernon Master Burns
 Tonnage 1319 Built at Liverpool When built 1864 - 10 mo
 By whom built Vernon Owners John Young & Co
 Port belonging to Liverpool Destined Voyage India via Liverpool
 If Surveyed Afloat or in Dry Dock Vernon Dry Dock

PLANS CASE

Burns 19/71

Last Survey, No. <u>8376</u>	Port of <u>Iron</u>	Classed <u>FAL</u> <i>S.S. Nos. by 10.70</i>
The present Condition of the		
Decks _____	Frames _____ <u>Paint</u>	Windlass and Capstan _____
Waterways _____	Breasthooks and Stems _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame at the Openings _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings _____	Ditto ditto at other places _____	Sails _____
Planksheers _____	Keelsons _____	Anchors, No. of _____
Sheerstrakes _____	Clamps and Shocks _____	Cables _____
Topsides _____	Ceiling _____	Hawsers and Warps _____
Wales _____	Rudder _____	Standing and Running Rigging _____
Plank (Bottom) and Counter _____	Copper <u>Lead</u> When put on <u>1864</u>	

Wood where seen

Wood where seen

Not to be supplied

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways Wood where Examined
Bottom cleaned and coated with Paint and Gallon.
Is now in good and efficient condition and in my
opinion eligible to remain reclassified.

Committee's Minute 12th September 1871
 Character assigned A 1

JTBW

© 2019
Lloyd's Register
Foundation
Certificate (if required).

120449-0258