

ANNUAL SURVEYS.

No. 636 Survey held at London Date 14th Sept. 1871
 on the Iron Ship Star of Greece Master Shaw
 Tonnage 1209 Built at Belfast When built 1868-9 mo
 By whom built Harland Owners Corry & Co
 Port belonging to Belfast Destined Voyage India
 If Surveyed Afloat or in Dry Dock Nigams' dry dock and afloat

Last Survey, No. 8566 Port of Iron Classed FAL

The present Condition of the

Decks	Trunnels <u>Rivets</u>	Windlass and Capstan
Waterways	Breasthooks and Stems	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors, No. of
Sheerstrakes	Clamps and Shells	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing and Running Rigging
Plank (Bottom) and Counter	Copper <u>plated</u> When put on <u>1868</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Bottom cleaned and coated with Patent Composition.
Is now in good and efficient condition, and in my
opinion eligible to remain as classed.

Committee's Minute 22nd September 1871.

Character assigned

Certificate (if required).

No. 635 Survey held at London Date 19th Sept. 1871
 on the Iron Ship Star of Erin Master Hills
 Tonnage 949 Built at Belfast When built 1862-10 mo
 By whom built Harland Owners Corry & Co
 Port belonging to Belfast Destined Voyage India
 If Surveyed Afloat or in Dry Dock Nigams dry dock

Last Survey, No. 8484 Port of Iron Classed FAL

The present Condition of the

Decks	Trunnels <u>Rivets</u>	Windlass and Capstan
Waterways	Breasthooks and Stems	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors, No. of
Sheerstrakes	Clamps and Shells	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing and Running Rigging
Plank (Bottom) and Counter	Copper <u>plated</u> When put on <u>1862</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Bottom cleaned and coated with Patent Composition.
Is now in good and efficient condition and in my
opinion eligible to remain as classed.

Committee's Minute 22nd September 1871.

Character assigned

Certificate (if required).