

# ANNUAL SURVEYS.

No. 636 Survey held at London Date 14<sup>th</sup> Sept. 1871  
 on the Iron Ship Star of Greece Master Shaw  
 Tonnage 1209 Built at Belfast When built 1868-9 mo  
 By whom built Harland Owners Corry & Co  
 Port belonging to Belfast Destined Voyage India  
 If Surveyed Afloat or in Dry Dock Nigams' dry dock and afloat

Last Survey, No. 8566 Port of Iron Classed FAL

The present Condition of the

Decks	<u>Good where seen</u>	Trunnels <u>Rivets</u>	Windlass and Capstan
Waterways		Breasthooks and Stems	Pumps
Comings		Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings		Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings		Ditto ditto at other places	Sails
Planksheers		Keelsons	Anchors, No. of
Sheerstrakes		Clamps and Shells	Cables
Topsides		Ceiling	Hawsers and Warps
Wales		Rudder	Standing and Running Rigging
Plank (Bottom) and Counter		Copper <u>plated</u> When put on <u>1868</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Good where examined

Bottom cleaned and coated with Patent Composition.  
Is now in good and efficient condition, and in my  
opinion eligible to remain as classed.

Committee's Minute 22<sup>nd</sup> September 1871.

Character assigned

Certificate (if required).

No. 635 Survey held at London Date 19<sup>th</sup> Sept. 1871  
 on the Iron Ship Star of Erin Master Hills  
 Tonnage 949 Built at Belfast When built 1862-10 mo  
 By whom built Harland Owners Corry & Co  
 Port belonging to Belfast Destined Voyage India  
 If Surveyed Afloat or in Dry Dock Nigams dry dock

Last Survey, No. 8484 Port of Iron Classed FAL

The present Condition of the

Decks	<u>Good where seen</u>	Trunnels <u>Rivets</u>	Windlass and Capstan
Waterways		Breasthooks and Stems	Pumps
Comings		Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings		Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings		Ditto ditto at other places	Sails
Planksheers		Keelsons	Anchors, No. of
Sheerstrakes		Clamps and Shells	Cables
Topsides		Ceiling	Hawsers and Warps
Wales		Rudder	Standing and Running Rigging
Plank (Bottom) and Counter		Copper <u>plated</u> When put on <u>1862</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Good where examined

Bottom cleaned and coated with Patent Composition.  
Is now in good and efficient condition and in my  
opinion eligible to remain as classed.

Committee's Minute 22<sup>nd</sup> September 1871.

Character assigned

Certificate (if required).