

ANNUAL SURVEYS.

No. 11577 Survey held at Newcastle Date 17th July 1871
 on the S. P. S. "Italia" Master Munro
 Tonnage 391 Built at Greenock When built 1869 - 7 mo
 By whom built Scott Owners Moore & Co.
 Port belonging to Glasgow Destined Voyage Barcelona
 If Surveyed Afloat or in Dry Dock Chelands Slip

Last Survey, No. 7279 Port of Iron Classed B I. 7.69.

The present Condition of the

Decks <u>Good where seen</u>	<u>Rivets</u> <u>Treenails</u> <u>Good where seen</u>	Windlass and Capstan <u>Good</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame at the Openings <u>"</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	<u>Ditto</u> ditto at other places <u>"</u>	Sails <u>Sufficient</u>
Planksheers <u>"</u>	Keelsons <u>"</u>	Anchors No. of <u>"</u>
Sheerstrakes <u>"</u>	Clamps and Shelves <u>"</u>	Cables <u>"</u>
Topsides <u>"</u>	Ceiling <u>"</u>	Hawsers and Warps <u>"</u>
Wales <u>"</u>	Rudder <u>"</u>	Standing & Running Rigging <u>"</u>
Plank (Bottom) and Counter <u>"</u>	Copper <u>"</u> When put on <u>"</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good where seen

This vessel appears to be in good and efficient condition, and eligible, in my opinion, to remain as classed.

Committee's Minute 2nd October 1871

Character assigned B I

R. J. Reed.
Damage Survey X 3.3.0
 Certificate (if required). Sept 10/71

No. _____ Survey held at _____ Date _____ 18____
 on the _____ Master _____
 Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____

The present Condition of the

Decks _____	Treenails _____	Windlass and Capstan _____
Waterways _____	Breasthooks and Stemson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame at the Openings _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings _____	Ditto ditto at other places _____	Sails _____
Planksheers _____	Keelsons _____	Anchors No. of _____
Sheerstrakes _____	Clamps and Shelves _____	Cables _____
Topsides _____	Ceiling _____	Hawsers and Warps _____
Wales _____	Rudder _____	Standing & Running Rigging _____
Plank (Bottom) and Counter _____	Copper _____ When put on _____	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways _____

Committee's Minute _____ 18____

Character assigned _____



© 2019

Lloyd's Register

Certificate (if required).