

ANNUAL SURVEYS.

No. 22089 Survey held at Liverpool Date 13th Sept^r 1871
 on the Iron B^k "Morle" Master Wills
 Tonnage 281 Built at London When built 1863 - 11 mo
 By whom built Westwood Owners Scuttin Hou
 Port belonging to London Destined Voyage Cemerara
 If Surveyed Afloat or in Dry Dock Clarence dry dock

Last Survey, No. 8990 Port of Iron. Classed *A 1
S.S. No. 67 71

The present Condition of the

Decks	} <u>where</u>	Treenails <u>Rivets</u>	} <u>Good</u>	Windlass and Capstan	} <u>Good</u>
Waterways		Breasthooks and Stemson		Pumps	
Comings	} <u>seen</u>	Transoms, Pointers, and Crutches	} <u>where</u>	Boats	} <u>supp</u>
Upper Deck Beams & Fastenings		Timbers of the Frame at the Openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings	} <u>Good</u>	Ditto ditto at other places	} <u>seen</u>	Sails	} <u>where</u>
Planksheers		Keelsons		Anchors No. of	
Sheerstrakes	} <u>seen</u>	Clamps and Shelves	} <u>seen</u>	Cables	} <u>seen</u>
Topsides		Ceiling		Hawsers and Warps	
Wales	} <u>seen</u>	Rudder	} <u>seen</u>	Standing & Running Rigging	} <u>seen</u>
Plank (Bottom) and Counter		Copper <u>Copper</u> When put on <u>1863</u>			

General Observations and Opinion, Bottom cleaned and coated - Periodical survey deferred until her return - she appears where seen in good condition and eligible in my opinion to continue as classed

Committee's Minute Liverpool 10th October 71 Wills B. C. Davey
 Character assigned *A 1

J. S. E. Certificate (if required)

No. 108 Survey held at Liverpool Date 29th & 30th Sept^r 1871
 on the Iron S. "Kunnington" Master Davies
 Tonnage 882 Built at Lancaster When built 1865 - 3 mo
 By whom built Turn I S Co Owners Wilson &
 Port belonging to Liverpool Destined Voyage Rangoon
 If Surveyed Afloat or in Dry Dock Clarence dry dock

Last Survey, No. 7247 Port of Iron. Classed *A 1
S.S. No. 69 69

The present Condition of the

Decks	} <u>Good</u>	Treenails <u>Rivets</u>	} <u>Good</u>	Windlass and Capstan	} <u>Good</u>
Waterways		Breasthooks and Stemson		Pumps	
Comings	} <u>where</u>	Transoms, Pointers, and Crutches	} <u>where</u>	Boats	} <u>supp</u>
Upper Deck Beams & Fastenings		Timbers of the Frame at the Openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings	} <u>seen</u>	Ditto ditto at other places	} <u>seen</u>	Sails	} <u>where</u>
Planksheers		Keelsons		Anchors No. of	
Sheerstrakes	} <u>seen</u>	Clamps and Shelves	} <u>seen</u>	Cables	} <u>seen</u>
Topsides		Ceiling		Hawsers and Warps	
Wales	} <u>seen</u>	Rudder	} <u>seen</u>	Standing & Running Rigging	} <u>seen</u>
Plank (Bottom) and Counter		Copper <u>Cement</u> When put on <u>1865</u>			

General Observations and Opinion, Bottom cleaned and painted, she is now in good condition and in my opinion may continue as classed

Committee's Minute Liverpool 10th October 71 Wills B. C. Davey
 Character assigned *A 1

J. S. E. Certificate (if required).

"Merle"

"
Wernington"
22989