

# ANNUAL SURVEYS.

No. 263 Survey held at London Date 12<sup>th</sup> Dec. 1871  
 on the iron ship 'Lennie' Headman Master Strachan  
 Tonnage 962 Built at Greenock When built 1869-11 mo  
 By whom built Scott Owners Union Ship & Company  
 Port belonging to Glasgow Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock Janab dry dock

Last Survey, No. 2430 Port of Iron Classed 11-70

The present Condition of the

Decks	Tree-nails <u>Rivets</u>	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper <u>Lead</u> When put on <u>1869</u>	

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways Good where examined  
Bottom cleaned and coated with Paint and Tallow  
Is now in good and efficient condition, and in my  
opinion eligible to remain as classed.  
 Committee's Minute 14<sup>th</sup> October 1871  
 Character assigned A 1 J.B.W.  
 Certificate (if required).

No. 138 Survey held at London Date 12<sup>th</sup> Dec. 1871  
 on the iron ship 'Isabel' Groom Master J. Auld  
 Tonnage 996 Built at Glasgow When built 1869-11 mo  
 By whom built Council Owners Brown & Son  
 Port belonging to Glasgow Destined Voyage India  
 If Surveyed Afloat or in Dry Dock On the Port of Victoria Dock

Last Survey, No. 7602 Port of Iron Classed 12-69

The present Condition of the

Decks	Tree-nails <u>Rivets</u>	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper <u>Lead</u> When put on <u>1869</u>	

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways Good where examined  
Bottom cleaned and coated with M. Linn's composition  
Is now in good and efficient condition, and in my  
opinion eligible to remain as classed.  
 Committee's Minute 17<sup>th</sup> October 1871  
 Character assigned A 1 J.B.W.  
 Certificate (if required).