

ANNUAL SURVEYS.

Iron.

No. 1139 Survey held at St. Shields Date 20th Sept 18 71
 on the Miella (Iron) Master E. Pitt
 Tonnage 727 Built at Newcastle When built 1865 - 8 mo
 By whom built Schlesinger Owners Hall Bros
 Port belonging to London Destined Voyage India
 If Surveyed Afloat or in Dry Dock J. Young's dock

Last Survey, No. 8130 Port of Iron.

Classed *A.I.
S.S. N^o 1-69. 7.70.

The present Condition of the

Decks good where seen

Waterways "

Comings "

Upper Deck Beams & Fastenings "

Lower Deck Beams & Fastenings "

Planksheers "

Sheerstrakes "

Topsides "

Wales "

Planks (Bottom) and Counter "

Rivets good where seen

Breasthooks and Stemson "

Transoms, Pointers, and Crutches "

Timbers of the Frame at the Openings "

Ditto ditto at other places "

Keelsons "

Clamps and Shelves "

Ceiling "

Rudder "

Copper When put on

Windlass and Capstan Good

Pumps "

Boats "

Masts, Yards, &c. "

Sails Sufficient

Anchors No. of do

Cables do

Hawsers and Warps do

Standing & Running Rigging do

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good where seen.

The bottom now scraped and painted: she appears to be in good and efficient condition, and eligible, in my opinion, to remain as classed.

Committee's Minute 24th Oct 18 71

Character assigned *A.I.

Certificate (if required).

No. 11394 Survey held at St. Shields Date 9th Oct 18 71
 on the Adelina (Iron) Master J. Cairnes
 Tonnage 731 Built at Newcastle When built 1864 - 7 mo
 By whom built Nitchell Owners Hall Bros
 Port belonging to London Destined Voyage India
 If Surveyed Afloat or in Dry Dock Middle dock

Last Survey, No. 8249 Port of Iron.

Classed *A.I.
S.S. N^o 1-69 9.70.

The present Condition of the

Decks good where seen

Waterways "

Comings "

Upper Deck Beams & Fastenings "

Lower Deck Beams & Fastenings "

Planksheers "

Sheerstrakes "

Topsides "

Wales "

Planks (Bottom) and Counter "

Rivets Good where seen

Breasthooks and Stemson "

Transoms, Pointers, and Crutches "

Timbers of the Frame at the Openings "

Ditto ditto at other places "

Keelsons "

Clamps and Shelves "

Ceiling "

Rudder "

Copper When put on

Windlass and Capstan Good

Pumps "

Boats "

Masts, Yards, &c. "

Sails Sufficient

Anchors No. of do

Cables do

Hawsers and Warps do

Standing & Running Rigging do

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good where seen

Bottom scraped and painted: she appears to be in good and efficient condition, and eligible, in my opinion, to remain as classed.

Committee's Minute 24th Oct 18 71

Character assigned *A.I.

Certificate (if required).