

# ANNUAL SURVEYS.

31954

No. 409 Survey held at London Date 24<sup>th</sup> Dec. 1871  
 on the iron ship 'British Flag' Master J. Mills  
 Tonnage 1265 Built at Liverpool When built 1866. 7 mo.  
 By whom built Various Owners British Ship Bn. Company  
 Port belonging to Liverpool Destined Voyage India  
 If Surveyed Afloat or in Dry Dock McGraws Dry Dock

Last Survey, No. 8435 Port of Iron

Classed FAI

The present Condition of the

Decks	Ironails <u>Rivets</u>	Windlass and Capstan
Waterways	Breasthooks and Stems	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors, No. of
Sheerstrakes	Clamps and Shells	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing and Running Rigging
Plank (Bottom) and Counter	Copper <u>Iron</u> When put on <u>1866</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good where examined

Bottom cleaned and coated with patent composition.  
Is now in good, and efficient condition, and in my  
opinion eligible to remain as classed.

Committee's Minute 24<sup>th</sup> October 1871

Character assigned \* A 1

Certificate (if required).

No. 418 Survey held at London Date 20<sup>th</sup> Dec. 1871

on the iron ship 'British Peer' Master Jackson

Tonnage 1330 Built at Belfast When built 1865. 1 mo

By whom built Harland Owners British Ship Bn. Company

Port belonging to Liverpool Destined Voyage India

If Surveyed Afloat or in Dry Dock McGraws Dry Dock

Last Survey, No. 8615 Port of Iron

Classed FAI

The present Condition of the

Decks	Ironails <u>Rivets</u>	Windlass and Capstan
Waterways	Breasthooks and Stems	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors, No. of
Sheerstrakes	Clamps and Shells	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing and Running Rigging
Plank (Bottom) and Counter	Copper <u>Iron</u> When put on <u>1865</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good where examined

Bottom cleaned and coated with patent composition  
Is now in good, and efficient condition, and in my  
opinion eligible to remain as classed.

Committee's Minute 24<sup>th</sup> October 1871

Character assigned \* A 1

Certificate (if required).