

ANNUAL SURVEYS.

No. 2322 Survey held at Liverpool Date 27th & 30th Oct^r 1871
 on the Iron B^o "Alice Davies" Master Craig
 Tonnage 590 Built at Liverpool When built 1868-10 mo
 By whom built Eaans Owners Davies &
 Port belonging to Liverpool Destined Voyage Pernambuco
 If Surveyed Afloat or in Dry Dock Clarence dry dock

Last Survey, No. 6774 Port of Iron. Classed *A 1
 12.68

The present Condition of the

Decks	} <u>Good</u>	Treenails <u>Rivets</u>	} <u>Good</u>	Windlass and Capstan	} <u>Good</u>
Waterways		Breasthooks and Stems		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the Openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings	} <u>where</u>	<u>Ditto</u> ditto at other places	} <u>where</u>	Sails	} <u>Supp</u>
Planksheers		Keelsons		Anchors No. of	
Sheerstrakes		Clamps and Shelves		Cables	
Topsides		Ceiling		Hawsers and Warps	
Wales	} <u>Seen</u>	Rudder	} <u>Seen</u>	Standing & Running Rigging	} <u>Seen</u>
Plank (Bottom) and Counter		Copper <u>Cement</u> When put on <u>1868</u>			
General Observations and Opinion,	Caulking of Bottom, Deck, and Waterways <u>Good</u>				

Bottom cleaned and painted. She is now in good condition and in my opinion may remain as Classed

Committee's Minute Liverpool 7th November 1871

Character assigned *A 1

J. G. E.

Certificate (if required)

No. 402 Survey held at Liverpool Date 26th Oct^r 1871
 on the Iron S. British Consul Master Raymond
 Tonnage 1267 Built at Liverpool When built 1866-8 mo
 By whom built Rayden Owners British Ship Co
 Port belonging to Liverpool Destined Voyage Sydney
 If Surveyed Afloat or in Dry Dock Clarence dry dock

Last Survey, No. 8573 Port of Iron. Classed *A 1
 S. S. No 1 London 12.70

The present Condition of the

Decks	} <u>Good</u>	Treenails <u>Rivets</u>	} <u>Good</u>	Windlass and Capstan	} <u>In good</u>
Waterways		Breasthooks and Stems		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the Openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings	} <u>where</u>	<u>Ditto</u> ditto at other places	} <u>where</u>	Sails	} <u>where</u>
Planksheers		Keelsons		Anchors No. of	
Sheerstrakes		Clamps and Shelves		Cables	
Topsides		Ceiling		Hawsers and Warps	
Wales	} <u>Seen</u>	Rudder	} <u>Seen</u>	Standing & Running Rigging	} <u>Seen</u>
Plank (Bottom) and Counter		Copper <u>Cement</u> When put on <u>1866</u>			
General Observations and Opinion,	Caulking of Bottom, Deck, and Waterways <u>Good</u>				

Bottom cleaned and painted. She is now in good condition and in my opinion may continue as Classed

Committee's Minute Liverpool 7th November 1871

Character assigned *A 1

J. G. E.

Certificate (if required).

"Alice Davies"
British Consul
23026



© 2019
Lloyd's Register
Foundation