

No. *169*

Survey held at

London 9511

Date

30th Oct^r 1871

18

On the

Iron Ship Florence

Master

J. Houston

Tonnage

841

Built at

Grainmouth

When built

1869

By whom built

Adamson

Owners

Adamson & Co.

Port belonging to

London

Destined Voyage

Singapore

If Surveyed Afloat or in Dry Dock

Bull head dry dock Millwall dock

Last Survey, No.

7871

Port of

Iron

Classed

*A. 1.**4.70*

The present Condition of the

Decks

good

Freenails

Rivets where seen good

Windlass and Capstan

in good order

Waterways

"

Breasthooks and Stenson

"

Pumps

"

Comings

"

Transoms, Pointers, and Crutches

"

Boats

"

Upper Deck Beams & Fastenings

"~~Timbers~~ of the Frame at the Openings*"*

Masts, Yards, &c.

"

Lower Deck Beams & Fastenings

"

Ditto ditto at other places

"

Sails

"

Planksheers

"

Keelsons

"

Anchors

No. of *3 B. 1 S. 2 K.**"*

Sheerstrakes

"

Clamps and Shelves

"

Cables

"

Topsides

"

Ceiling

"

Hawsers and Warps

"

Wales

"

Rudder

*efficient**"*

Standing & Running Rigging

"

Plank (Bottom) and Counter

"

Copper

When put on

"

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

*good**Survey'd in Ballast.**Clean'd and recoated the bottom.**she is as far as seen in good condition and in my opinion entitled to remain as*

Committee's Minute

10th November 1871

Character assigned

A 1

Certificate (if required):