

9525  
**ANNUAL SURVEYS.**

*31674*

No. *414* on the *Iron Screw Hutton Chaytor* Master *—*  
 Survey held at *London* Date *21<sup>st</sup> Octr., 8* 18*71*  
 Tonnage *580* Built at *Newcastle* When built *1855*  
 By whom built *459* Owners *Genl Iron Screw Col<sup>rs</sup> Comp<sup>y</sup>*  
 Port belonging to *London* Destined Voyage *Coasting*  
 If Surveyed Afloat or in Dry Dock *Commercial Dry dock*

Last Survey, No. *7880* Port of *Iron.* Classed *A. 1. 55/1103-70*  
*4-70*

The present Condition of the

Decks <i>good</i>	Treenails <i>Rivets where seen</i> <i>good</i>	Windlass and Capstan <i>in good order</i>
Waterways <i>"</i>	Breasthooks and Stemson <i>"</i>	Pumps <i>"</i>
Comings <i>"</i>	Transoms, Pointers, and Crutches <i>"</i>	Boats <i>"</i>
Upper Deck Beams & Fastenings <i>"</i>	<del>Timbers</del> of the Frame at the Openings <i>"</i>	Masts, Yards, &c. <i>"</i>
Lower Deck Beams & Fastenings <i>"</i>	Ditto ditto at other places <i>"</i>	Sails <i>"</i>
Planksheers <i>"</i>	Keelsons <i>"</i>	Anchors No. of <i>3 B. 15. 2 K</i> <i>"</i>
Sheerstrakes <i>"</i>	Clamps and Shelves <i>"</i>	Cables <i>"</i>
Topsides <i>"</i>	Ceiling <i>"</i>	Hawsers and Warps <i>"</i>
Wales <i>"</i>	Rudder <i>efficient</i> <i>"</i>	Standing & Running Rigging <i>"</i>
<del>Plank</del> (Bottom) and Counter <i>"</i>	Copper <i>When put on</i> <i>"</i>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways *good.*

*Fitted New Iron Comings to the Main Hatchways.*  
*Clean'd and recoated the bottom, She is as far as seen in*  
*good condition and is in my opinion entitled*  
*to remain as class'd*  
*Samuel Persons*  
 Certificate (if required)

Committee's Minute

Character assigned

Recd. 7. 11. 71

IRON 449-0439



Hutton Chaytor  
Flower



© 2019

Lloyd's Register  
Foundation