

# ANNUAL SURVEYS.

No. 23068 Survey held at Birkenhead Date Nov 27 - 28 1871  
 on the Iron S "Centaur" Master M Wilding  
 Tonnage 1571 Built at London When built 1864 - 11 mo  
 By whom built Messrs J C Owners Fletcher & Co  
 Port belonging to L'pool Destined Voyage India  
 If Surveyed Afloat or in Dry Dock Great-Flour-graving dock

Last Survey, No. 7576 Port of Lon. Classed \* A-1  
 (S.S. No. 1-69) 69

The present Condition of the

Decks	Freemasts <u>Pivots</u>	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps <u>Good</u>
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors, No. of <u>efficient</u>
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps <u>where</u>
Wales	Rudder	Standing and Running Rigging <u>seen</u>
Plank (Bottom) and Counter	Copper <u>Cem</u> When put on <u>64</u>	

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways Satisfactory

The bottom scraped & painted. Is now in good condition  
& in my opinion eligible to remain as Classed

Committee's Minute Liverpool 12<sup>th</sup> December, 1871. E. C. Wheeler

Character assigned \* A-1 7.9.2. Certificate (if required).

No. 108 Survey held at Birkenhead Date Dec 2 - 6 1871  
 on the Iron S "Delaware" Master J Preston  
 Tonnage 3243 Built at Ile of Man When built 1865 - 8 mo  
 By whom built 25-97 J. M. S. B. C. Owners C. Dixon  
 Port belonging to L'pool Destined Voyage India  
 If Surveyed Afloat or in Dry Dock Great-Flour-graving dock

Last Survey, No. 9310 Port of Iron. Classed \* A-1  
 (S.S. No. 1-69) 71

The present Condition of the

Decks	Freemasts <u>Pivots</u>	Windlass and Capstan <u>Good</u>
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails <u>efficient</u>
Planksheers	Keelsons	Anchors, No. of
Sheerstrakes	Clamps and Shelves	Cables <u>where</u>
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing and Running Rigging <u>seen</u>
Plank (Bottom) and Counter	Copper <u>Cem</u> When put on <u>65-66-67</u>	

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways Satisfactory

The bottom scraped & painted & propeller refitted. Is  
now in good condition & in my opinion eligible to  
remain as Classed


Committee's Minute Liverpool 12<sup>th</sup> December, 1871. E. C. Wheeler

Character assigned \* A-1 7.9.2. Certificate (if required).



THE LLOYD'S REGISTER

"  
Bentley  
" 2019  
Belmonte 23068



Lloyd's Register  
Foundation