

ANNUAL SURVEYS.

295 No. 9636 Survey held at London Date 28th November 1871
 on the iron ship "Colton Abbey" Master Melligan
 Tonnage 1194 Built at Birkenhead When built 1864 5 mo
 By whom built Clarke Owners Porter Bros.
 Port belonging to Liverpool Destined Voyage Singapore via Cardiff
 If Surveyed Afloat or in Dry Dock In the Port of Victoria Docks

Last Survey, No. 8627 Port of Iron Classed *A1
 (S. S. No. 1-67) 1.71

The present Condition of the

Decks	Freencils <u>Rivets</u>	Windlass and Capstan
Waterways	Breasthooks and Stems	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper <u>sent</u> When put on <u>1864</u>	

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways good where examined
Bottom cleaned and coated with Paint.
Is now in good and efficient condition and in my opinion eligible to remain as classed.
 Committee's Minute 15th Dec^r 1871 M. Turner
 Character assigned *A1 T.P.W.

Certificate (if required).

105 No. 9636 Survey held at London Date 7th Dec^r 1871
 on the iron ship "Hartfell" Master Modrell
 Tonnage 1224 Built at Glasgow When built 1864 2 mo
 By whom built Barclay Owners M. Romey
 Port belonging to Liverpool Destined Voyage India
 If Surveyed Afloat or in Dry Dock on the Port of Victoria Docks

Last Survey, No. 8628 Port of Iron Classed *A1
 (S. S. No. 1-68) 1.71

The present Condition of the

Decks	Freencils <u>Rivets</u>	Windlass and Capstan
Waterways	Breasthooks and Stems	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper <u>sent</u> When put on <u>1864</u>	

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways good where examined
Bottom cleaned and coated with Zinc and Sallow.
Is now in good and efficient condition and in my opinion eligible to remain as classed.
 Committee's Minute 18th Dec^r 1871 M. Turner
 Character assigned *A1 T.P.W.

Certificate (if required).