

No. *11070* Survey held at *V. Shields 9753* Date *December 10<sup>th</sup> 1871*  
on the *W. Lutterworth* Master *J. B. Reid*  
Tonnage *22.3* Built at *Aultpool* When built *1868* — *11 mo*  
By whom built *Denton* Owners *Milham & Co*  
Port belonging to *London* Destined Voyage *Rangoon*  
If Surveyed Afloat or in Dry Dock *Wilson's dry dock*

Last Survey, No. *6770* Port of *Iron* Classified *\*A.I.* *12.68.*

The present Condition of the

Decks <i>Good when seen</i>	<i>Rivet</i> Freenails <i>good when seen</i>	Windlass and Capstan <i>Good</i>
Waterways <i>do</i>	Breasthooks and Stemson <i>do</i>	Pumps <i>do</i>
Comings <i>do</i>	Transoms, Pointers, and Crutches <i>do</i>	Boats <i>do</i>
Upper Deck Beams & Fastenings <i>do</i>	Timbers of the Frame at the Openings <i>do</i>	Masts, Yards, &c. <i>do</i>
Lower Deck Beams & Fastenings <i>do</i>	<i>Ditto</i> ditto at other places <i>do</i>	Sails <i>sufficient</i>
Planksheers <i>do</i>	Keelsons <i>do</i>	Anchors No. of <i>do</i>
Sheerstrakes <i>do</i>	Clamps and Shelves <i>do</i>	Cables <i>do</i>
Topsides <i>do</i>	Ceiling <i>do</i>	Hawsers and Warps <i>do</i>
Wales <i>do</i>	Rudder <i>do</i>	Standing & Running Rigging <i>do</i>
Plank (Bottom) and Counter <i>do</i>	<i>Copper</i> — When put on —	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways *good when seen.*

*The bottom has now been scraped and painted: she appears to be in good and efficient condition, and eligible, in my opinion, to remain as classed.*

Committee's Minute *30<sup>th</sup> January 1872*

Character assigned

*\*A.I.*

*J. B. Reid*

*J. B. Reid*

Certificate (if required).