

# REPORT of SURVEY for REPAIRS.

No. in Reg. Book. 369 No. 1871 Survey held at LONDON Date, first Survey 4 Dec Last Survey 25 Dec  
on the Iron Ship "Roslin Castle" Master J. Christie  
Tonnage 1170 built at Glasgow When built 1863. 7mo  
By whom built Hapier Owners Currie & Co  
Port belonging to Liverpool Destined Voyage Salcutta  
If Surveyed Afloat or in Dry Dock By "McGraw's" Dry dock and Afloat.  
Last Survey, No. 7726 Port Iron. Classed \*FAI  
REPAIRS, &c.

## REPAIRS, &c.

1 S. 1401-68, 12-70

The timber boards and ceiling equal to three strokes fore and aft on each side removed.

Windows unhang, wood binnings stopped, and the chain cables ranged on deck for Examination.

The parts Exposed by the removal of ceiling -  
have been cleaned and painted and a large pro-  
-portion of the ceiling in the lower hold renewed of Pine.  
Bottom cleaned and coated with patent Composition.

### *Present Condition of the*

Decks		Treenails	Good	Windlass and Capstan	Good
Waterways		Breasthooks and Stems		Pumps	—
Comings		Transoms, Pointers, and Crutches		Boats	—
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c.	—
Lower Deck Beams & Fastenings		Ditto Ditto at other places		Condition, how ascertained	Seen from Head
Planksheers		Keelsons		Sails	Good
Sheerstrakes		Clamps and Shelves		Anchors No. of	Good
Sides		Ceiling		Cables	and
		Rudder		Hawsers and Warps	Insufficient
		Copper	When put on 1863	Standing & Running Rigging	
		Caulking of	Good where examined		
(Bottom) and Counter		Bottom, Deck, & Waterways			
Room Skylights		Coal Bunker, Openings, Lids, &c.		Scuppers	Good
Observations and Opinion,				Cargo and Main Hatchways	Good
				Hatches	Good

Is now in good and efficient condition  
and in my opinion eligible to remain as passed  
and be marked (S. S. #2-71)

Amount of Entry Fee.....£ — : — : is received by me,

Special.....4 : 4 :

*Certificate (if required)* : 3 :

Minute 2<sup>nd</sup> February 1872

*signed*

S. S. No. 2-71

W. H. Warner

© 2019

Lloyd's Register  
Foundation

1R0N450-0222