

9/21/72

ANNUAL SURVEYS.

No. 23149 Survey held at LiverpoolDate 18th 30 January 1872on the SHIP "STRATHBLAINE" Master J. RoeTonnage 1364 Built at GlasgowWhen built 1868 10moBy whom built BarnesOwners S. & A. AllanPort belonging to GlasgowDestined Voyage CalcuttaIf Surveyed Afloat or in Dry Dock Brunswick Dry DockLast Survey, No. 9457 Port of Sum.Classed * A S

12.70.

The present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Treenails Planks

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the Openings

Ditto ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper Cement When put on 1868

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Sails

Anchors No. of

Cables

Hawsers and Warps

Standing & Running Rigging

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good where seen

She is now in good condition. Eligible in my opinion to remain as classed.

Committee's Minute Liverpool 13th February 1872Character assigned * A 1

J. G. E.

Certificate (if required)

No. 240 Survey held at LiverpoolDate 16th 8 February 1872on the SHIP "GLENESK"Master MillardTonnage 1298 Built at LiverpoolWhen built 1869 10moBy whom built RoydenOwners Alexander & CoPort belonging to LiverpoolDestined Voyage CalcuttaIf Surveyed Afloat or in Dry Dock Brunswick Dry DockLast Survey, No. 7666 Port of Gron.Classed * A S

11.69.

The present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Treenails Planks

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the Openings

Ditto ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper Cement When put on 1869

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Sails

Anchors No. of

Cables

Hawsers and Warps

Standing & Running Rigging

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good where seen

She is now in good condition. Eligible in my opinion to remain as classed.

Committee's Minute Liverpool 13th February 1872Character assigned * A 1

J. G. E.

Certificate (if required).

120450-0244

Wernick

Wernick

