

ANNUAL SURVEYS.

No. 11689 Survey held at St. Shields Date 8th January 1872
 on the S.S. "Mang" Master
 Tonnage 544 Built at Wentlepool When built 1871 - 4 mo
 By whom built Johnston & Co. Owners
 Port belonging to Montrose Destined Voyage
 If Surveyed Afloat or in Dry Dock Wilson's dock

Last Survey, No. 9003 Port of Iron. Classed 90 A 1.
5.71.

present Condition of the	present Condition of the	present Condition of the
keels <u>good where seen</u>	Rivets <u>good where seen</u>	Windlass and Capstan <u>good</u>
waterways <u>do</u>	Breasthooks and Stemson <u>do</u>	Pumps <u>do</u>
rudders <u>do</u>	Transoms, Pointers, and Crutches <u>do</u>	Boats <u>do</u>
upper Deck Beams & Fastenings <u>do</u>	Timbers of the Frame at the Openings <u>do</u>	Masts, Yards, &c. <u>do</u>
lower Deck Beams & Fastenings <u>do</u>	Ditto ditto at other places <u>do</u>	Sails <u>sufficient</u>
sternsheers <u>do</u>	Keelsons <u>do</u>	Anchors No. of <u>do</u>
sternstrakes <u>do</u>	Clamps and Shelves <u>do</u>	Cables <u>do</u>
sternsides <u>do</u>	Ceiling <u>do</u>	Hawsers and Warps <u>do</u>
sternles <u>do</u>	Rudder <u>do</u>	Standing & Running Rigging <u>do</u>
stern (Bottom) and Counter <u>do</u>	Copper <u>do</u> When put on <u>do</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Bottom now scraped and painted: she appears to be in good and efficient condition, and eligible, in my opinion, to remain as classed.

Committee's Minute 16th February 1872

Character assigned 90 A 1

Certificate (if required)

180450-0253