

# ANNUAL SURVEYS.

32135

No. 9303 Survey held at London Date 18 Feb 72  
 on the iron screw steamer "Viceroy" Master Saylor  
 Tonnage 2177 Built at London When built 1871-7 mo  
 By whom built Meek Owners Beith, Meek  
 Port belonging to London Destined Voyage India  
 If Surveyed Afloat or in Dry Dock Beith, Meek's dry dock

Last Survey, No. 9305 Port of Iron Classed 100 A  
 The present Condition of the  
 Decks Good where seen Treenails Rivets Windlass and Capstan  
 Waterways Good where seen Breasthooks and Stenson Pumps  
 Comings Good where seen Transoms, Pointers, and Crutches Boats  
 Upper Deck Beams & Fastenings Good where seen Timbers of the Frame at the Openings Masts, Yards, &c.  
 Lower Deck Beams & Fastenings Good where seen Ditto ditto at other places Sails  
 Planksheers Good where seen Keelsons Anchors, No. of  
 Sheerstrakes Good where seen Clamps and Shells Cables  
 Topsides Good where seen Ceiling Rudder  
 Wales Good where seen Copper 100 A When put on 1871 Standing and Running Rigging  
 Plank (Bottom) and Counter Good where seen  
 General Observations and Opinion, Caulking of Bottom, Deck, and Waterways Good where examined  
Bottom cleaned and coated with Patent Composition  
Is now in good and efficient condition and in  
my opinion eligible to remain as classed.  
 Committee's Minute 16 Feb 72 1872  
 Character assigned 100 A W. H. Turner  
 Certificate (if required).

No. 194 Survey held at London Date 18 Feb 72  
 on the iron screw steamer "Akai" Master P. Witt  
 Tonnage 1472 Built at Newcastle When built 1870-4 mo  
 By whom built Leslie Owners Ross & St. Mary's (P&O)  
 Port belonging to Odessa Destined Voyage Odessa  
 If Surveyed Afloat or in Dry Dock Shames dry dock

Last Survey, No. 8534 Port of Iron Classed 100 A  
 The present Condition of the  
 Decks Good where seen Treenails Rivets Windlass and Capstan  
 Waterways Good where seen Breasthooks and Stenson Pumps  
 Comings Good where seen Transoms, Pointers, and Crutches Boats  
 Upper Deck Beams & Fastenings Good where seen Timbers of the Frame at the Openings Masts, Yards, &c.  
 Lower Deck Beams & Fastenings Good where seen Ditto ditto at other places Sails  
 Planksheers Good where seen Keelsons Anchors, No. of  
 Sheerstrakes Good where seen Clamps and Shells Cables  
 Topsides Good where seen Ceiling Rudder  
 Wales Good where seen Copper 100 A When put on 1870 Standing and Running Rigging  
 Plank (Bottom) and Counter Good where seen  
 General Observations and Opinion, Caulking of Bottom, Deck, and Waterways Good where examined  
Bottom cleaned and coated with McAlister's Composition  
Is now in good and efficient condition and in  
my opinion eligible to remain as classed.  
 Committee's Minute 16 Feb 72 1872  
 Character assigned 100 A W. H. Turner  
 Certificate (if required).