

ANNUAL SURVEYS.

No. 633 Survey held at London Date 13th Feb^y 1872
 on the iron ship "Star of Denmark" Master Margue
 Tonnage 998 Built at Belfast When built 1863 & mo
 By whom built Kasland Owners Corry & Co
 Port belonging to Belfast Destined Voyage India
 If Surveyed Afloat or in Dry Dock Meyram's dry dock and Afloat

Last Survey, No. 9123 Port of Irish Classed SAI 6.71

The present Condition of the

Decks	<i>Good where seen</i>	Treenails <u>Rivets</u>	Windlass and Capstan
Waterways		Breasthooks and Stemson	Pumps
Comings		Transoms, Painters, and Crutches	Boats
Upper Deck Beams & Fastenings		Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings		Ditto ditto at other places	Sails
Planksheers		Keelsons	Anchors, No. of
Sheerstrakes		Clamps and Shatts	Cables
Topsides		Ceiling	Hawsers and Warps
Wales		Rudder	Standing and Running Rigging
Plank (Bottom) and Counter		Copper <u>Comb</u> When put on <u>1863</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good where examined

Rudder pintles repaired. Bottom cleaned and coated with patent composition. Is now in good and efficient condition, and in my opinion eligible to remain as classed.

Committee's Minute 20th Feb^y 1872

Character assigned

A1

TDW

Certificate (if required).

120N450-0280