

ANNUAL SURVEYS.

No. 2488 Survey held at Liverpool. Date 14 Feb to 2 March 1872
 on the SHIP "NAGPORE" Master Benjamin Morris
 Tonnage 1521 Built at N. Spl. When built 1865. 1. mo
 By whom built Pile Owners Mackinnon & Co
 Port belonging to Liverpool Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock Dueson Dry Dock.

Last Survey, No. 8683 Port of Iron. Classed * A 1
 s. s. 1871. 69. 1.71

The present Condition of the

Decks	Freemasts <u>Reels.</u>	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors, No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing and Running Rigging
Plank (Bottom) and Counter	Copper <u>Cement</u> When put on <u>1865</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good where seen.

Bottom scraped and painted. She is now in good condition. Eligible in my opinion remain as classed.

Committee's Minute Liverpool 15th March 1872.

Character assigned * A 1

Certificate (if required).

No. 86 Survey held at Liverpool. Date 26 Feb to 8 March 1872
 on the SHIP "WAVE QUEEN" Master Snclair
 Tonnage 853 Built at Glasgow When built 1861. 10 mo
 By whom built Stephen Owners Alison & Co
 Port belonging to Glasgow Destined Voyage Stago
 If Surveyed Afloat or in Dry Dock Brunswick Dry Dock.

Last Survey, No. 7952 Port of Iron. Classed * A 1
 s. s. 1872. 70. 3.70

The present Condition of the

Decks	Freemasts <u>Reels.</u>	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors, No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing and Running Rigging
Plank (Bottom) and Counter	Copper When put on	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good where seen.

Bottom scraped and painted. She is now in good condition. Eligible in my opinion remain as classed.

Committee's Minute Liverpool 15th March 1872.

Character assigned * A 1

Certificate (if required).

NEW YORK

1818

Wool & Lincen

Magpie

23188



© 2019

Lloyd's Register Foundation