

ANNUAL SURVEYS.

Rec 28/8/72

No. 11738 Survey held at Newcastle Date 2nd March 1872.
 on the Iron S.S. "Hilda" Master J. Shotton
 Tonnage 650 Built at 1st Glasgow When built 1865 - 5 Mo.
 By whom built Reid Owners Yetteren Mining Co. Limited.
 Port belonging to London Destined Voyage Norway
 If Surveyed Afloat or in Dry Dock Cleland's Patent Slip.

Last Survey, No. 2070 Port of Iron. Classified A1.
4, 71.
 S.S. No. 2-69.

The present Condition of the

Decks <u>Good where seen</u>	Treenails <u>Rivets</u>	Good where seen	Windlass and Capstan <u>Good.</u>
Waterways <u>do.</u>	Breasthooks and Stemson <u>do.</u>		Pumps <u>do.</u>
Comings <u>do.</u>	Transoms, Pointers, and Crutches <u>do.</u>		Boats <u>4 in No.</u> <u>do.</u>
Upper Deck Beams & Fastenings <u>do.</u>	Timbers of the Frame at the Openings <u>do.</u>		Masts, Yards, &c. <u>do.</u>
Lower Deck Beams & Fastenings <u>do.</u>	<u>Framing</u> <u>do.</u>		Sails <u>Sufficient</u>
Planksheers <u>do.</u>	Ditto <u>ditto</u> at other places <u>do.</u>		Anchors No. of <u>3 B. 1 S. 2 H.</u>
Sheerstrakes <u>do.</u>	Keelsons <u>do.</u>		Cables <u>Complete not ranged.</u>
Topsides <u>do.</u>	Clamps and Shelves <u>Stringers</u> <u>do.</u>		Hawsers and Warps <u>Well found</u>
Wales <u>do.</u>	Ceiling <u>do.</u>		Standing & Running Rigging <u>Good.</u>
Plank (Bottom) and Counter <u>do.</u>	Rudder <u>do.</u>		
	Copper <u>When put on</u>		

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways Good where tried.
This vessel's bottom has been scraped and coated, she appears to be in a good and efficient condition, and fit in my opinion to remain as classed
 Committee's Minute 2nd April 1872 A1.
 Character assigned A1 J. H. Cooke.

Certificate (if required)

No. _____ Survey held at _____ Date _____ 18____
 on the _____ Master _____
 Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____

The present Condition of the

Decks _____	Treenails _____	Windlass and Capstan _____
Waterways _____	Breasthooks and Stemson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame at the Openings _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings _____	Ditto ditto at other places _____	Sails _____
Planksheers _____	Keelsons _____	Anchors No. of _____
Sheerstrakes _____	Clamps and Shelves _____	Cables _____
Topsides _____	Ceiling _____	Hawsers and Warps _____
Wales _____	Rudder _____	Standing & Running Rigging _____
Plank (Bottom) and Counter _____	Copper _____ When put on _____	

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways _____

Committee's Minute _____ 18____
 Character assigned _____



© 2019

Lloyd's Register
 Foundation

Certificate (if required).

120N450-0413