

ANNUAL SURVEYS.

No. 306 Survey held at London Date 11 March 18 72
 on the Sentinel "Saxeritch" Master J. Girard
 Tonnage 1910 Built at Newcastle When built 1869 11 mo
 By whom built Leslie Owners Russ. St. Narg. Trading Comp.
 Port belonging to London Destined Voyage Black Sea
 If Surveyed Afloat or in Dry Dock Shames Limited dry dock

Last Survey, No. 8915 Port of Iron. Classed B/I
1, 71

The present Condition of the

Decks	<u>Keels</u> <u>Rivets</u>	Windlass and Capstan
Waterways	Breasthooks and Stems	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors, No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing and Running Rigging
Plank (Bottom) and Counter	Copper <u>Iron</u> When put on <u>1869</u>	

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways Good where examined
Bottom cleaned and coated with patent composition
is now in good and efficient condition, and
in my opinion eligible to remain as classed.

Committee's Minute 5 April 18 72
 Character assigned B/I ITDW W. H. Jones
 Certificate (if required).

No. 343 Survey held at London Date 22 March 18 72
 on the Sentinel "Lloyds" Master Parkman
 Tonnage 246 Built at Newcastle When built 1869 5 mo
 By whom built Palmer Owners Dixon & Co
 Port belonging to London Destined Voyage Mediterranean via Cardiff
 If Surveyed Afloat or in Dry Dock on the Victoria Dock Boat

Last Survey, No. 9049 Port of Iron. Classed B/I
6, 71

The present Condition of the

Decks	<u>Keels</u> <u>Rivets</u>	Windlass and Capstan
Waterways	Breasthooks and Stems	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors, No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing and Running Rigging
Plank (Bottom) and Counter	Copper <u>Asp.</u> When put on <u>1869</u>	

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways Good where examined
Inside cleaned and painted. Bottom coated with Red-
lead and Gallon, caulked weather deck.
Is now in good and efficient condition, and in

Committee's Minute 5 April 18 72 my opinion eligible to remain
 Character assigned B/I as classed. W. H. Jones
 Certificate (if required).