

# ANNUAL SURVEYS.

No. 3261 Survey held at Bristol Date 18 April 18 72  
on the "Onyx" Master W. Hatch  
Tonnage 120 Built at Sunderland When built 1864  
By whom built Laird Owners Weatherly  
Port belonging to Sunderland Destined Voyage Bristol to Sharncliffe  
If Surveyed Afloat or in Dry Dock Dry Dock

Last Survey, No. 9452 Port of Weymouth Classed A1 Sup SS. 117 69

The present Condition of the

Decks <u>Good</u>	Treenails <u>Good</u>	Windlass and Capstan <u>Good</u>
Waterways <u>do</u>	Breasthooks and Stemson <u>do</u>	Pumps <u>do</u>
Comings <u>do</u>	Transoms, Pointers, and Crutches <u>do</u>	Boats <u>Three</u>
Upper Deck Beams & Fastenings <u>do</u>	Timbers of the Frame at the Openings <u>do</u>	Masts, Yards, &c. <u>do</u>
Lower Deck Beams & Fastenings <u>do</u>	Ditto ditto at other places <u>do</u>	Sails <u>well found</u>
Planksheers <u>do</u>	Keelsons <u>do</u>	Anchors No. of <u>213 1 S Sledge</u>
Sheerstrakes <u>do</u>	Clamps and Shelves <u>do</u>	Cables <u>Complete</u>
Topsides <u>do</u>	Ceiling <u>do</u>	Hawsers and Warps <u>suft</u>
Wales <u>do</u>	Rudder <u>do</u>	Standing & Running Rigging <u>good</u>
Plank (Bottom) and Counter <u>do</u>	Copper <u>Bottom</u> When put on <u>April 1872</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good

Bottom scraped, and coated with two coats of Red Lead and one of white do, and one of Tallow. She is now in good Condition.

Committee's Minute 23rd April 18 72

Character assigned B

IVBW John Congdon  
Certificate (if required).

No. \_\_\_\_\_ Survey held at \_\_\_\_\_ Date \_\_\_\_\_ 18 \_\_\_\_\_  
on the \_\_\_\_\_ Master \_\_\_\_\_  
Tonnage \_\_\_\_\_ Built at \_\_\_\_\_ When built \_\_\_\_\_  
By whom built \_\_\_\_\_ Owners \_\_\_\_\_  
Port belonging to \_\_\_\_\_ Destined Voyage \_\_\_\_\_  
If Surveyed Afloat or in Dry Dock \_\_\_\_\_

Last Survey, No. \_\_\_\_\_ Port of \_\_\_\_\_ Classed \_\_\_\_\_

The present Condition of the

Decks _____	Treenails _____	Windlass and Capstan _____
Waterways _____	Breasthooks and Stemson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame at the Openings _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings _____	Ditto ditto at other places _____	Sails _____
Planksheers _____	Keelsons _____	Anchors No. of _____
Sheerstrakes _____	Clamps and Shelves _____	Cables _____
Topsides _____	Ceiling _____	Hawsers and Warps _____
Wales _____	Rudder _____	Standing & Running Rigging _____
Plank (Bottom) and Counter _____	Copper _____ When put on _____	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways \_\_\_\_\_

Committee's Minute \_\_\_\_\_ 18 \_\_\_\_\_

Character assigned \_\_\_\_\_



© 2019

Lloyd's Register  
Foundation

Certificate (if required).

120N450-0504