

10038 ANNUAL SURVEYS.

322847

No. 283 Survey held at London Date 17th April 1872
 on the Iron Ship "Golden Fleece" Master W. Rife
 Tonnage 1257 Built at Glasgow When built 1869 bmo
 By whom built Barday Owners James Michael
 Port belonging to Greenock Destined Voyage India
 If Surveyed Afloat or in Dry Dock James Dry Dock

Last Survey, No. 8445 Port of Iron Classed Fall
2.71

The present Condition of the

Decks	<u>Greenails</u> <u>Pirets</u>	Windlass and Capstan
Waterways	Breasthooks and Stenson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Bitts ditto at other places	Sails
Planksheers	Keelsons	Anchors, No. of
Sheerstrakes	Clamps and Shells	Cables
Topsides	Ceiling	Hawsers and Warps
Vales	Rudder	Standing and Running Rigging
Plank (Bottom) and Counter	Copper <u>Iron</u> When put on <u>1869</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good where examined

Bottom cleaned and coated with Paint and Gallon.
Is now in good and efficient condition, and in
my opinion eligible to remain as classed.

Committee's Minute 30th April 1872

Char acter assigned A. A.

J. W. M. A. Turner
 Certificate (if required).

1202450-0515