

ANNUAL SURVEYS.

57253

12 No. Survey held at London Date 13th April 1872
 on the iron Ship "Balkamah" Master Richardson
 Tonnage 1378 Built at Kalb When built 1866. 3 mo
 By whom built Hunt's Iron Works Owners E. Bates
 Port belonging to Liverpool Destined Voyage India
 If Surveyed Afloat or in Dry Dock Both. Hunt's dry dock and Afloat

Last Survey, No. 7995 Port of Iron Classed Fall
S.S. Lond 1-701 5-70

The present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

General Observations and Opinion,

Greenails

Breasthooks and Stenson

Transoms, Pointers, and Crutches

Timbers of the Frame at the Openings

Ditto ditto at other places

Keelsons

Clamps and Shells

Ceiling

Rudder

Copper

When put on 1866

Caulking of Bottom, Deck, and Waterways

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Sails

Anchors, No. of

Cables

Hawsers and Warps

Standing and Running Rigging

Bottom cleaned and coated with Paint and Gallon.
Is now in good and efficient condition. and in my
opinion eligible to remain as classed.

Committee's Minute 30th April 1872

Character assigned

T. D. W. M. Turner

Certificate (if required).

408 No. Survey held at London Date 14th April 1872
 on the iron Ship "British Envoy" Master C. S. Clements
 Tonnage 1265 Built at Liverpool When built 1866-4 mo
 By whom built Royden Owners British Ship Store
 Port belonging to Liverpool Destined Voyage India
 If Surveyed Afloat or in Dry Dock James Limited dry dock

Last Survey, No. 9060 Port of Iron Classed Fall
S.S. Lond 1-701 5-71

The present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

General Observations and Opinion,

Greenails

Breasthooks and Stenson

Transoms, Pointers, and Crutches

Timbers of the Frame at the Openings

Ditto ditto at other places

Keelsons

Clamps and Shells

Ceiling

Rudder

Copper

When put on 1866

Caulking of Bottom, Deck, and Waterways

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Sails

Anchors, No. of

Cables

Hawsers and Warps

Standing and Running Rigging

Bottom cleaned and coated with Paint and Gallon.
Is now in good and efficient condition. and in my
opinion eligible to remain as

Committee's Minute 30th April 1872

Character assigned

T. D. W. M. Turner

Certificate (if required).