

ANNUAL SURVEYS.

10189

Rec 8/6/72

No. 6172 Survey held at Greenock Date 13th 15th & 17th April 1872
 on the Iron Ship "Colmonell" Master J. Scobie
 Tonnage 1255 Built at Port Glasgow When built 1871 6th Month
 By whom built John Reid & Co. Owners John Kerr & Co.
 Port belonging to Greenock Destined Voyage Glyde to Liverpool & Calcutta
 If Surveyed Afloat or in Dry Dock In dry dock

Last Survey, No. 5967 Port of Port Glasgow Iron Classed 100 As 6/71

The present Condition of the	
Decks <u>Good where seen</u>	Treenails <u>Rivets</u> <u>Good where seen</u>
Waterways <u>do do</u>	Breasthooks and Stemson <u>do do</u>
Comings <u>do do</u>	Transoms, Pointers, and Crutches <u>do do</u>
Upper Deck Beams & Fastenings <u>do & firm</u>	Timbers of the Frame at the Openings <u>do do</u>
Lower Deck Beams & Fastenings <u>do & firm</u>	Ditto ditto at other places <u>do do</u>
Planksheers <u>Good where seen</u>	Keelsons <u>do do</u>
Sheerstrakes <u>Plating do do</u>	Clamps and Shelves <u>do do</u>
Topsides <u>do do do</u>	Ceiling <u>do do</u>
Wales <u>do do do</u>	Rudder <u>do do</u>
Plank (Bottom) and Counter <u>do do do</u>	Copper <u>Bottom Coated</u> When put on <u>do do</u>
Windlass and Capstan <u>Good</u>	
Pumps <u>do</u>	
Boats <u>do</u>	
Masts, Yards, &c. <u>do</u>	
Sails <u>Well found</u>	
Anchors No. of <u>3 Bowers & 2 Stream & 2 Kedges</u>	
Cables <u>Complete</u>	
Hawsers and Warps <u>Sufficient</u>	
Standing & Running Rigging <u>Good</u>	

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways Good where examined.
Now dry, vessel placed in dry dock, cleaned down and bottom coated with Red lead and Grease. This vessel has been examined throughout, and where seen found in good and efficient condition, and we are of opinion she is eligible to remain as classed 100 As.

Committee's Minute 11th June 1872 H. B. S. M.
 Character assigned 100 J. M. Edwin Bouchman
 Certificate (if required).

No. _____ Survey held at _____ Date _____ 18____
 on the _____ Master _____
 Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____	
The present Condition of the	
Decks _____	Treenails _____
Waterways _____	Breasthooks and Stemson _____
Comings _____	Transoms, Pointers, and Crutches _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame at the Openings _____
Lower Deck Beams & Fastenings _____	Ditto ditto at other places _____
Planksheers _____	Keelsons _____
Sheerstrakes _____	Clamps and Shelves _____
Topsides _____	Ceiling _____
Wales _____	Rudder _____
Plank (Bottom) and Counter _____	Copper _____ When put on _____
Windlass and Capstan _____	
Pumps _____	
Boats _____	
Masts, Yards, &c. _____	
Sails _____	
Anchors No. of _____	
Cables _____	
Hawsers and Warps _____	
Standing & Running Rigging _____	

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways _____
 Committee's Minute _____ 18____
 Character assigned _____
 Certificate (if required).

