

ANNUAL SURVEYS.

388 No. Survey held at London Date 12th June 1872
 on the Iron Ship Allahabad Master J. Crispin
 Tonnage 1186 Built at Liverpool When built 1864 9th msk.
 By whom built Potter Owners J. Stephens
 Port belonging to London Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock Princes dry dock &

Last Survey, No. 6666 Port of Iron. Classed A. 1. S. S. No. 3/70 11, 70

The present Condition of the

Decks	good	Timber	Rivets	where seen	Windlass and Capstan	in good order
Waterways	"	Breasthooks and Stemson		good	Pumps	"
Comings	"	Transoms, Pointers, and Crutches		"	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings		"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto ditto at other places		"	Sails	"
Planksheers	"	Keelsons		"	Anchors, No. of <u>3 B. 1 S. 2 K</u>	"
Sheerstrakes	"	Clamps and Shelves		"	Cables	"
Topsides	"	Ceiling		"	Hawsers and Warps	"
Wales	"	Rudder <u>efficient</u>		"	Standing and Running Rigging	"
Plank (Bottom) and Counter	"	Copper		When put on		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

She is in good condition, and entitled to remain as classed A. 1.
Samuel Presons

Committee's Minute 25th June 1872

Character assigned A. 1

Certificate (if required).

109 No. Survey held at London Date 18th June 1872
 on the Iron Ship Kirkham Master R. Macfarlan
 Tonnage 1061 Built at Birkenhead When built 1856
 By whom built Owners Anderson & Co.
 Port belonging to London Destined Voyage
 If Surveyed Afloat or in Dry Dock Horse Ferry dry dock &

Last Survey, No. 9227 Port of Iron. Classed A. 1. S. S. No. 3/71 11, 71

The present Condition of the

Decks	good	Timber	Rivets	where seen	Windlass and Capstan	in good order
Waterways	"	Breasthooks and Stemson		good	Pumps	"
Comings	"	Transoms, Pointers, and Crutches		"	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings		"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto ditto at other places		"	Sails	"
Planksheers	"	Keelsons		"	Anchors, No. of <u>3 B. 1 S. 2 K</u>	"
Sheerstrakes	"	Clamps and Shelves		"	Cables	"
Topsides	"	Ceiling		"	Hawsers and Warps	"
Wales	"	Rudder <u>efficient</u>		"	Standing and Running Rigging	"
Plank (Bottom) and Counter	"	Copper		When put on		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Cleaned & recoated her outside. Repaired or made good the Pop deck

She is in good condition and entitled to remain as classed


Committee's Minute 25th June 1872

Character assigned A. 1

Samuel Presons

Certificate (if required).

Mhalabes
Kordun



© 2019

Lloyd's Register
Foundation