

# ANNUAL SURVEYS.

32444

No. 630 Survey held at London Date 19<sup>th</sup> June 18 72  
 on the Shen M<sup>r</sup> "Europa" Master Campbell  
 Tonnage 576 Built at Newcastle When built 1862. 3mo  
 By whom built Palmer Owners London M<sup>r</sup> Ship Company  
 Port belonging to London Destined Voyage Mediterranean  
 If Surveyed Afloat or in Dry Dock On the Pontoon Victoria Docks, and afloat.

Last Survey, No. 9026 Port of Iron. Classed 95 A1  
 (5.5. Nre. No. 2-70) 5.71

The present Condition of the

Decks	<u>Ironails</u> <u>Rivets</u>	Windlass and Capstan
Waterways	Breasthooks and Stems	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors, No. of
Sheerstrakes	Clamps and Shells	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing and Running Rigging
Plank (Bottom) and Counter	Copper	When put on

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Bottom cleaned and coated with Paint and Gallon.  
Is now in good and efficient condition and in my  
opinion eligible to remain as classed.

Committee's Minute 5<sup>th</sup> July 18 72

Character assigned 95 A1

M. Surve

ITW

Certificate (if required).

No. 236 Survey held at London Date 24<sup>th</sup> June 18 72  
 on the Shen M<sup>r</sup> "Henry Morton" Master J. J. Douglas  
 Tonnage 986 Built at Newcastle When built 1860. 10mo  
 By whom built Palmer Owners Cory & Son  
 Port belonging to London Destined Voyage Newcastle  
 If Surveyed Afloat or in Dry Dock On the Pontoon Victoria Docks and afloat.

Last Survey, No. 9286 Port of Iron. Classed 95 A1  
 (5.5. Nre. No. 1-71) 6.71

The present Condition of the

Decks	<u>Ironails</u> <u>Rivets</u>	Windlass and Capstan
Waterways	Breasthooks and Stems	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors, No. of
Sheerstrakes	Clamps and Shells	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing and Running Rigging
Plank (Bottom) and Counter	Copper	When put on

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Bottom cleaned and coated with Paint and Gallon.  
Is now in good and efficient condition and in my  
opinion eligible to remain as classed.

Committee's Minute 5<sup>th</sup> July 18 72

Character assigned A1

M. Surve

ITW

Certificate (if required).