

ANNUAL SURVEYS.

32444

No. 630 Survey held at London Date 19th June 18 72
 on the Shen M^r "Europa" Master Campbell
 Tonnage 576 Built at Newcastle When built 1862. 3mo
 By whom built Palmer Owners London M^r Ship Company
 Port belonging to London Destined Voyage Mediterranean
 If Surveyed Afloat or in Dry Dock On the Pontoon Victoria Docks, and afloat.

Last Survey, No. 9026 Port of Iron. Classed 95 A1
 (5.5. Nre. No. 2-70) 5.71

The present Condition of the

| | | |
|-------------------------------|--------------------------------------|------------------------------|
| Decks | <u>Ironails</u> <u>Rivets</u> | Windlass and Capstan |
| Waterways | Breasthooks and Stems | Pumps |
| Comings | Transoms, Pointers, and Crutches | Boats |
| Upper Deck Beams & Fastenings | Timbers of the Frame at the Openings | Masts, Yards, &c. |
| Lower Deck Beams & Fastenings | Ditto ditto at other places | Sails |
| Planksheers | Keelsons | Anchors, No. of |
| Sheerstrakes | Clamps and Shells | Cables |
| Topsides | Ceiling | Hawsers and Warps |
| Wales | Rudder | Standing and Running Rigging |
| Plank (Bottom) and Counter | Copper | When put on |

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Bottom cleaned and coated with Paint and Gallon.
Is now in good and efficient condition and in my
opinion eligible to remain as classed.

Committee's Minute 5th July 18 72

Character assigned 95 A1

M. Surve

ITW

Certificate (if required).

No. 236 Survey held at London Date 24th June 18 72
 on the Shen M^r "Henry Morton" Master J. J. Douglas
 Tonnage 986 Built at Newcastle When built 1860. 10mo
 By whom built Palmer Owners Cory & Son
 Port belonging to London Destined Voyage Newcastle
 If Surveyed Afloat or in Dry Dock On the Pontoon Victoria Docks and afloat.

Last Survey, No. 9286 Port of Iron. Classed 95 A1
 (5.5. Nre. No. 1-71) 6.71

The present Condition of the

| | | |
|-------------------------------|--------------------------------------|------------------------------|
| Decks | <u>Ironails</u> <u>Rivets</u> | Windlass and Capstan |
| Waterways | Breasthooks and Stems | Pumps |
| Comings | Transoms, Pointers, and Crutches | Boats |
| Upper Deck Beams & Fastenings | Timbers of the Frame at the Openings | Masts, Yards, &c. |
| Lower Deck Beams & Fastenings | Ditto ditto at other places | Sails |
| Planksheers | Keelsons | Anchors, No. of |
| Sheerstrakes | Clamps and Shells | Cables |
| Topsides | Ceiling | Hawsers and Warps |
| Wales | Rudder | Standing and Running Rigging |
| Plank (Bottom) and Counter | Copper | When put on |

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Bottom cleaned and coated with Paint and Gallon.
Is now in good and efficient condition and in my
opinion eligible to remain as classed.

Committee's Minute 5th July 18 72

Character assigned A1

M. Surve

ITW

Certificate (if required).