

REPORT of SURVEY for REPAIRS.

No. in
Reg. Book.

No. 2164

Survey held at

Belfast

Date, first Survey

20th May

Last Survey

30th May

1872

on the

Ship

Glencoe

Master

Wm. J. G. G. G.

Tonnage

746

built at

Lumberton

When built

1853

By whom built

Owners

Hutton and Co.

Port belonging to

Glasgow

Destined Voyage

If Surveyed Afloat or in Dry Dock

Afloat

Last Survey, No.

6097/768

Port of

Greenock

Classed

A. I. 2/70.

REPAIRS, &c.

The owners intended carrying out the provisions of S.S.W.I. at this port; but being pressed for the vessel by the charterers, they were obliged to abandon it until her return to this country. As it appears from a letter from the Secretary dated the 4th May, the Committee have agreed to. The Greenock report on this vessel No. 6.097 forwarded with Secretary's letter one dated the 25th May is herewith returned.

Present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Engine Room Skylights

Coal Bunker, Openings, Lids, &c.

Scuppers

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained

Sails

Anchors No. of

Cables

Hawsers and Warps

Standing & Running Rigging

Cargo and Main Hatchways

Hatches

General Observations and Opinion,

The several parts of the interior of this vessel could not be seen as she was lined throughout for carrying cargo: as far as seen she appeared to be in good and efficient condition and fit, in my opinion, to remain classed A. I.

The Amount of Entry Fee.....£

is received by me,

Special.....

Certificate (if required)

Committee's Minute

18

Character assigned



© 2019

Lloyd's Register
Foundation

LRN451-0297