

10384
ANNUAL SURVEYS.

32783

No. 331 Survey held at London Date 23rd July 1872
 on the Iron Screw Charente Master John Dew
 Tonnage 395 Built at Middlesboro When built 1865
 By whom built Backhouse Owners London & Yorkshire S.S. Comp^y
 Port belonging to London Destined Voyage Coasting
 If Surveyed Afloat or in Dry Dock Nelson Pass Slip

Geelong

Last Survey, No. 10092 Port of Iron Classed A.1 S.S. No. 1/90
4.72

The present Condition of the

Decks	<u>good</u>	Treenails	<u>Rivets good where seen</u>	Windlass and Capstan	<u>in good order</u>
Waterways	"	Breasthooks and Stemson	"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"	Sails	"
Plank sheers	"	Keelsons	"	Anchors, No. of	<u>3 1/2, 1 S, 2 K</u>
Sheerstrakes	"	Clamps and Shelves	"	Cables	"
Topsides	"	Ceiling	"	Hawsers and Warps	"
Wales	"	Rudder	<u>efficient</u>	Standing and Running Rigging	"
Plank (Bottom) and Counter	"	Copper	When put on		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good.

Examined the bottom and on the port side at the bilge, renew'd about thirty rivets. — — — She is now in good condition and in my opinion is entitled to remain as class'd A.1

Committee's Minute 2nd August 1872
 Character assigned A.1

J.P.M. Samuel Presious
 Certificate (if required).

No. _____ Survey held at _____ Date _____ 18____
 on the _____ Master _____
 Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Plank sheers	Keelsons	Anchors, No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing and Running Rigging
Plank (Bottom) and Counter	Copper	When put on

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways _____

Committee's Minute _____ 18____

Character assigned _____



© 2019
 Lloyd's Register
 Foundation
 Certificate (if required).