

ANNUAL SURVEYS.

10419
22503

No. 1480 Survey held at London Date July 16th 18 72.
on the S. S. Anolo Dane Master Andersen
Tonnage 646 Built at Newcastle When built 1866-7
By whom built Lesslie Owners United Steam S. Co.
Port belonging to Copenhagen Destined Voyage Baltic
If Surveyed Afloat or in Dry Dock Linthouse Dry Dock

Last Survey, No. 10316 Port of Iron Classed B 5.69
S. S. N. 1. 69.

The present Condition of the

Decks <u>Good</u>	Treenails <u>Where run good</u>	Windlass and Capstan <u>Good</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame at the Openings <u>"</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Ditto <u>ditto</u> at other places <u>"</u>	Sails <u>"</u>
Planksheers <u>"</u>	Keelsons <u>"</u>	Anchors, No. of <u>3 B. 1 S. 2 1/2</u>
Sheerstrakes <u>"</u>	Clamps and Shelves <u>"</u>	Cables <u>Good</u>
Topsides <u>"</u>	Ceiling <u>"</u>	Hawsers and Warps <u>Good</u>
Wales <u>"</u>	Rudder <u>"</u>	Standing and Running Rigging <u>Sufficient</u>
Plank (Bottom) and Counter <u>"</u>	Copper <u>Cement</u> When put on <u>"</u>	
General Observations and Opinion,	Caulking of Bottom, Deck, and Waterways <u>Good</u>	

*The Bottom cleaned and coated with Blacklead
She is now in good condition and in my opinion
eligible to remain as classed.*

Committee's Minute 13th August 18 72.
Character assigned B 1 J. Lawrence
Certificate (if required).

No. _____ Survey held at _____ Date _____ 18 ____
on the _____ Master _____
Tonnage _____ Built at _____ When built _____
By whom built _____ Owners _____
Port belonging to _____ Destined Voyage _____
If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____

The present Condition of the

Decks _____	Treenails _____	Windlass and Capstan _____
Waterways _____	Breasthooks and Stemson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame at the Openings _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings _____	Ditto <u>ditto</u> at other places _____	Sails _____
Planksheers _____	Keelsons _____	Anchors, No. of _____
Sheerstrakes _____	Clamps and Shelves _____	Cables _____
Topsides _____	Ceiling _____	Hawsers and Warps _____
Wales _____	Rudder _____	Standing and Running Rigging _____
Plank (Bottom) and Counter _____	Copper _____ When put on _____	
General Observations and Opinion,	Caulking of Bottom, Deck, and Waterways _____	

Committee's Minute _____ 18 ____
Character assigned _____