

ANNUAL SURVEYS.

19/1/74
10439
No. 2337 Survey held at Liverpool Date June 26 to 29 1872
on the Don B. "Helen Isabel" Master Ralston
Tonnage 250 Built at Greenock When built 1869 p.m.
By whom built Robertson Owners Baine & Co.
Port belonging to Greenock Destined Voyage N. America
If Surveyed Afloat or in Dry Dock In Canning graving dock

Last Survey, No. 1343 Port of Iron Classed * 1.70

The present Condition of the

Decks	Trunnels <u>Pivots</u>	Windlass and Capstan <u>Good</u>
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c. <u>efficient</u>
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors, No. of <u>where</u>
Sheerstrakes	Clamps and Shells	Cables
Topsides	Ceiling	Hawsers and Warps <u>seen</u>
Wales	Rudder	Standing and Running Rigging
Plank (Bottom) and Counter	Copper <u>Cen</u> When put on <u>69</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good

The bottom scraped & painted. Is now in good condition & in my opinion eligible to remain as Classed —

Committee's Minute Liverpool 20th August 1872

Character assigned A 1 m.c.

E. C. Wheeler

Certificate (if required).

No. 840 Survey held at Birkenhead Date July 29 to Aug 2 1872
on the Don L. "Atholl" Master A. Asplet
Tonnage 1395 Built at Glasgow When built 1870 p.m.
By whom built Stephen Owners J. Warrington
Port belonging to Leith Destined Voyage South America
If Surveyed Afloat or in Dry Dock In Messrs. Clovers graving dock m.c.

Last Survey, No. 8194 Port of Iron Classed 95-A 1

The present Condition of the

Decks	Trunnels <u>Pivots</u>	Windlass and Capstan <u>Good</u>
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c. <u>efficient</u>
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors, No. of <u>where</u>
Sheerstrakes	Clamps and Shells	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing and Running Rigging <u>seen</u>
Plank (Bottom) and Counter	Copper <u>Cen</u> When put on <u>70</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good

The bottom scraped & painted. Is now in good condition & in my opinion eligible to remain as Classed —

Committee's Minute Liverpool 20th August 1872

Character assigned 95-A 1

E. C. Wheeler

Certificate (if required).

"Helen Isabel."
23.3.77
"O. Hall"



© 2019

Lloyd's Register
Foundation