

114 No. 114 Survey held at London ^{Change of owners -} Date April 15th/₄ 1872
 on the S. "Victoria Pyanza" (Iron) Master Brown
 Tonnage 1022 Built at Belfast When built 1863 8 moths for receiving
 By whom built Harland Owners G. H. Fletcher Change of owners
 Port belonging to Liverpool Destined Voyage Cardiff applying for
 If Surveyed Afloat or in Dry Dock Regents dry dock 20 April 72
not paid.

Last Survey, No.	Port of	Classed
		<u>*A</u>
		S.S. No. 1. 66
The present Condition of the		
Decks	Frames	Windlass and Capstan
Waterways	Breasthooks and Stenson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper When put on	

Good

Good

sufficient

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways where seen good

The outside of this vessel has now been examined for S.S. No. 2 and the remainder of the survey is to be completed at ^{Middlesbrough} Cardiff where the ballast will be discharged - Eligible in my opinion to remain

Committee's Minute 18 classed *A Jos. W. Wain

Character assigned _____ Certificate (if required).

New 1874/75

1202452.0006

