

No. 201 Survey held at London 10500 Date 30th August 1872 32040
on the iron ship 'Dobderru fash' Master J. Mossan
Tonnage 989 Built at Sunderland When built 1863 11 mo
By whom built Donald Owners Hushes
Port belonging to Liverpool Destined Voyage Melbourne
If Surveyed Afloat or in Dry Dock on the Victoria Dock Pontoon.

Last Survey, No. 9428 Port of Crown Classed SAI
The present Condition of the (S.S. Liverpool 71) 9-71
Decks Good where seen Treennails Pirets Windlass and Capstan _____
Waterways _____ Breasthooks and Stemson _____ Pumps _____
Comings _____ Transoms, Pointers, and Crutches _____ Boats _____
Upper Deck Beams & Fastenings _____ Timbers of the Frame at the Openings _____ Masts, Yards, &c. _____
Lower Deck Beams & Fastenings _____ Ditto ditto at other places _____ Sails _____
Planksheers _____ Keelsons _____ Anchors, No. of _____
Sheerstrakes _____ Clamps and Shelves _____ Cables _____
Topsides _____ Ceiling _____ Hawesers and Warps _____
Wales _____ Rudder _____ Standing and Running Rigging _____
Plank (Bottom) and Counter _____ Copper 1000 When put on 1863

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways Good where examined
Rudder pintles repaired. Bottom cleaned, and coated
with Paint and Sallor. Is now in good and efficient
condition, and in my opinion
eligible to remain as classed.
Committee's Minute 3rd September 1872
Character assigned A

TDW

M. Surner

Certificate (if required).