

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. 183 No. 10375 Iron Survey held at London Date, first Survey July 15 Last Survey August 7 1872
 on the S. White Eagle (Iron) Master W. Andrews
 Tonnage 878 built at Glasgow When built 1855
 By whom built Bylbe Owners Bylbe
 Port belonging to London Destined Voyage Australia
 If Surveyed Afloat or in Dry Dock Regents dr. dock & W.S. Dock
 Last Survey, No. 9437 Port Iron Classed * A 1
 REPAIRS, &c. S.S. No 1.68 3.71

The main deck renewed with 3 in. Pine, about 160 ft of Waterway with Seals, the poop deck with 3 inch Pine and the Poop and forecastle cants with Pitco Pine — Windlass unhung but not stripped —
 The bottom coated with Gibbs' antifouling mixture —

Present Condition of the

Decks	} <u>Good</u> <u>where seen</u>	Treenails	} <u>where seen</u>	Windlass and Capstan	} <u>Good</u> <u>&</u> <u>sufficient</u>
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Ditto Ditto at other places		Condition, how ascertained	
Planksheers		Keelsons		Sails	
Sheerstrakes		Clamps and Shelves		Anchors No. of	
Topsides		Ceiling		Cables	
Wales		Rudder		Hawsers and Warps	
Plank (Bottom) and Counter		Copper		Standing & Running Rigging	
Engine Room Skylights	Caulking of				
Coal Bunker, Openings, Lids, &c.	Bottom, Deck, & Waterways	Scuppers	Cargo and Main Hatchways	Hatches	

General Observations and Opinion, good

This vessel is now in good order, and is eligible in my opinion to remain as classed * A 1

The Amount of Entry Fee.....£ 2 : — : is received by me,
 Special..... 1 : 1 :
 Certificate (if required) : 5 :

Thos. McEwan

Committee's Minute 28th August 1872

Character assigned * A 1

record repair



© 2019

Lloyd's Register Foundation