

ANNUAL SURVEYS.

Rec 14/9/72

No. 1821 Survey held at Southampton Date 10th Sept 18 72
 on the S. S. Mavis Master JR Church
 Tonnage 264 Built at Hartlepool When built 1871
 By whom built Withy Owners J Howard & Co
 Port belonging to London Destined Voyage Coaster
 If Surveyed Afloat or in Dry Dock Dry Dock

Last Survey, No. 9690 Port of Hartlepool Classed 90 A 1
 The present Condition of the 1872

Decks	Good	Treenails	Rivet	Good	Windlass and Capstan	Good
Waterways	"	Breasthooks and Stemson		"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches		"	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings		"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto ditto at other places		"	Sails	Good & Sufficient
Planksheers		Keelsons		"	Anchors, No. of	3 B. 4 S. 2 K
Sheerstrakes	"	Clamps and Shelves		"	Cables	300 Fathoms
Topsides	"	Ceiling		"	Hawsers and Warps	Good & Sufficient
Wales	"	Rudder		"	Standing and Running Rigging	"
Plank (Bottom) and Counter	"	Copper	Paint	When put on	Now	

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways Good
This Vessel has had her Butts cemented, been scraped & coated with two coats of red lead, is appearing in very good condition & in my opinion eligible to remain as classed 90 A 1
 Committee's Minute 20th September 1872
 Character assigned 90 A 1 Davidson
Certificate (if required).

No. _____ Survey held at _____ Date _____ 18 ____
 on the _____ Master _____
 Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____
 The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors, No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing and Running Rigging
Plank (Bottom) and Counter	Copper	When put on

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways _____
 Committee's Minute _____ 18 ____
 Character assigned _____
Certificate (if required).



Warrant of Arrest

✓

h

