

ANNUAL SURVEYS.

No. 260 Survey held at London Date Sept 14 to 17 1872
 on the Iron Ship "River Nith" Master W Crawford
 Tonnage 1128 Built at Newcastle When built 1869 4m
 By whom built Schlusger Owners Stargrove & Co
 Port belonging to Liverpool Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock Princes Dry Dock

Last Survey, No. 9536 Port of Iron Classed *A.1

The present Condition of the

Decks <u>good</u>	Fastenings <u>Rivets</u> <u>good</u>	Windlass and Capstan <u>good</u>
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings <u>where</u>	Ditto ditto at other places <u>where</u>	Sails <u>where</u>
Planksheers <u>painted</u>	Keelsons	Anchors, No. of
Sheerstrakes <u>4</u>	Clamps and Shelves	Cables
Topsides <u>7</u>	Ceiling <u>seen</u>	Hawsers and Warps
Vales <u>4</u> <u>seen</u>	Rudder	Standing and Running Rigging <u>seen</u>
Plank (Bottom) and Counter <u>painted</u>	Copper Cement When put on <u>1869</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good where seen

now done, bottom scraped and painted
She is now, where seen, in good condition
fit in my opinion to remain as classed

Committee's Minute 20th September 1872

Character assigned

TDW J. Morish
 Certificate (if required).

No. 52 Survey held at London Date Sept 11 to 17 1872
 on the Iron Ship "Zealandia" Master W. A. Curry
 Tonnage 1116 Built at Glasgow When built 1869 6m
 By whom built Cornell Owners Shaw Saville & Co
 Port belonging to London Destined Voyage New Zealand
 If Surveyed Afloat or in Dry Dock Lincolns Dry Dock & East India Dock

Last Survey, No. 9256 Port of Iron Classed *A.1

The present Condition of the

Decks <u>good</u>	Fastenings <u>Rivets</u> <u>good</u>	Windlass and Capstan <u>good</u>
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings <u>where</u>	Ditto ditto at other places <u>where</u>	Sails <u>where</u>
Planksheers <u>painted</u>	Keelsons	Anchors, No. of
Sheerstrakes <u>4</u>	Clamps and Shelves	Cables
Topsides <u>4</u>	Ceiling <u>seen</u>	Hawsers and Warps <u>seen</u>
Vales <u>4</u> <u>seen</u>	Rudder	Standing and Running Rigging
Plank (Bottom) and Counter <u>painted</u>	Copper Cement When put on <u>1869</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good where seen

now done, bottom scraped and painted
She is now, where seen, in good condition
fit in my opinion to remain as classed

Committee's Minute 20th September 1872

Character assigned

TDW J. Morish
 Certificate (if required).